





			Eversource Transmission Lines: F107
TYPE OF INSPECTION:Weekly	/ X_Storm EventInc	identCorrective Action	
Date: 01/27/20 Time: 8:00am Does this report include a 0.25" storm event? X Yes No If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge X Weather Station Storm event information is from Pease Air Force Base.			Madbury, Durham, Newington, Portsmouth, NH Alteration of Terrain Permit: SEC Docket No. 2015-004
+Storm event information (approx.):	Start date: 01-25-20 Start date: Start date:	Amount (inches): 1.19in Amount (inches): Amount (inches):	Environmental Permit: SEC Docket No. 2015-004 USEPA NOI Tracking No:
NOTE: *			NHR1000QN NHR1000QT NHR1000QO <u>NHR1000S6</u>
			NAI Project No: <u>23840.39</u>
Inspector name(s), title(s) and qualifications: Matthew Smith, Normandeau Environmental Inspector and Marc Jacobs, CPESC, NHCWS			
Others present/qualifications(s): Sam Eames, Eversource construction representative			
Weather conditions (since last inspection): Clear, with high temperatures in the 30's.			
Weather conditions (time of inspection & future outlook): Clear, high temperatures in the 30's. Future forecast is clear with a chance of snow showers over the weekend with temperatures in the 30's.			
CONSTRUCTION SITE SEQUENCING AND DISTURBANCE Disturbed area and ongoing work (acreage & description): < 1 acre			
Proceeding per approved plan? <u>X</u> YesNo, if not, note area and explain:			
Operating within phasing limitations? X	esNo, if not, note	e area and explain:	

General Comments

- Continued BMP maintenance and upkeep is a constant priority on shorelines of both sides of the Bay during the winter months.
- Housekeeping such as sweeping of timber mats and roads is a must.
- All required BMPs need to be installed before construction activities.
- All contractors on site should have a copy of the construction drawings.
- During mat removal be sure to remove any remains of silt socks etc.

Work completed this week:

- Portsmouth
 - No construction activities.
- Newington
 - No construction activities.
- Durham.
 - o MJ continues to drill foundation for Str. 58.

Erosion and sediment control items and observations:

- BMPs
 - o All required BMPs need to be installed as access roads are being built, before construction starts.
 - Rill on upper slope resulted in sediment build up at silt fence at Getchell property/west side of the Bay.
 Location is on the south side, at the top of slope. Routine maintenance is warranted. See Figures 11 and 12.

Corrective Action

None

Eversource Seacoast Reliability Project

OPERATING WITHIN LIMITS? N/A X_YESNO if not, please explain:			
SURFACE WATER QUALITY			
Storm water discharge from the site at the time of inspection? Storm water discharge consistent with water quality standards? Turbidity visually observed? If yes, check appropriate location(s) below, and describe discharge: Location: N/A			
Pond location: N/A Adjacent surface water or wetland: N/A			
Description: N/A.			
TEMPORARY EROSION AND SEDIMENT CONTROLS (TESC)			
Installed and functioning per the SWPPP? _X YESNO _N/A			
Are any corrective actions required?YESX_NO if so, please describe? * Note: The permit differentiates between conditions requiring repairs and maintenance, and those requiring corrective action. Corrective actions are triggered only for specific, more serious conditions and require a corrective action form be filled out. Please refer to Part 5 of the CGP for additional information			
PERMANENT EROSION AND SEDIMENTATION CONTROLS			
Disturbed areas must have a uniform perennial vegetative cover with 85% density, or equivalent physical stabilization, to be considered permanently stabilized (per the SWPPP).			
Installed and functioning per the SWPPP? _X_YESNON/A			
If not, explain what was not performed correctly (construction/stabilization) for each of the following categories. Detail what/where needs to be corrected, and what has been corrected since the last monitoring inspection. If so, what areas: N/A			
Areas that have been restored and mulched, but have little germination: Both sides of Little Bay. Trench between Strs. 106-107 (Frink farm-Hannah Lane). Strs. 28 & 29. Moderate germination: Strs. 135 – 139. Stabilized (85%+ germination): Field house at UNH, Colovos Rd at UNH, and College Brook at UNH.			
OTHER COMMENTS AND OBSERVATIONS: -None other than the above comments.			
CERTIFICATION:			
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."			
This form is completed and signed in accordance with the Signatory Requirements specified in Appendix I.11 of the NPDES CGP for the project site and NOI identified above.			
Authorized signature:			



Fig 1: Access to Str. 71. Viewing west (01-27-20).



Fig 3: Stream DS19, east of Str. 70. No turbid water visible. (01-27-20).



Fig 2: Str. 70 work area, note straw cover. Viewing east. (01-27-20).



Fig 4: Access road through wetland DW9, between Strs. 65 and 66. Viewing west. Note stump grindings on slopes. (01-27-20).



Fig 5: Access road to Str. 58 of off route 108. Bridge through wetland DW29. Viewing west. (01-27-20).



Fig 7: Str. 48. Viewing north. (01-27-20).



Fig 6: Access road to Str. 47. Viewing north. (01-27-20).



Fig 8: Soil spoils from drilling Str. 58 spread in turtle bed area between Strs. 48 and 49. Area is enclosed with straw bales. Turtle area is not Complete. Viewing west. (01-27-20).



Fig 9: Access road between Strs. 51 and 52. Bridge over stream DS46. Viewing northeast. (01-27-20).



Fig 11: Rill on top of slope at Getchell property/west side of the Bay. Viewing southwest. (01-27-20).



Fig 10: Str. 99 at Getchell property/west side of the Bay. Viewing west. (01-27-20).



Fig 12: Sediment build-up on silt fence, runoff from rills at Getchell property/west side of the Bay. Viewing southeast. (01-27-20)



Fig 13: BMPs installed on slope at Getchell property/west side of the Bay. Viewing north. (01-27-20).



Fig 15: BMPs installed on slope at Gundalow landing/east side of the Bay. Viewing west. (01-27-20).



Fig 14: BMPs installed at toe of slope at Getchell property/west side of the Bay. Viewing east. (01-27-20).



Fig 16: Turbidity barrier in intertidal zone at Gundalow landing/east side of the Bay. Viewing west. (01-27-20).

Construction Monitoring Report #47

Eversource Seacoast Reliability Project

PROJECT TEAM

Eversource

Attn: Dena Champy-Eversource Project

Manager

Phone: 603-634-2891

Email: dena.champy@eversource.com

Attn: Tom Sullivan-Construction

Management

Phone: 078-502-3805

Email: thomas.sullivan@eversource.cm

Attn: Joseph Sperry-Eversource Senior

Engineer

Phone: 603-634-2562

Email: joseph.sperry@eversource.com

Attn: Kurt Nelson-Eversource Permitting

Phone: 603-714-3031

Email: <u>kurt.nelson@eversource.com</u>

Attn: Lauren Cote-Municipal Outreach

Phone: 603-634-2409

Email: <u>lauren.cote@eversource.com</u>

Attn: Sam Eames-Construction Rep

Phone: 603-915-0073

Email: sam.eames@eversource.com

Attn: Thomas Meister-Construction Rep

Phone: 339-987-7901

Email: Thomas.meister@eversource.com

Attn: Joshua Scott-ROW Safety Mgr

Phone: 603-848-7759

Email: <u>Joshua.scott@eversource.com</u>

Contractors

JCR Utility Construction Co., Inc.

Attn: Matt Moreau-Project Manager

Phone: 603-895-4062

Email: matt.moreau@crutility.com

McCourt Construction

Attn: Michael Worhunsky-Project Manager

Phone: 617-293-3864

Email:mworhunsky@mccourtconstruction.com

Attn: Scott Gorman-Safety Director

Phone: 617-828-8822

Email: sgorman@mccourtconstruction.com

Attn: Dan Cedrone-Superintendant

Phone: 617-908-2660

Email: dcedrone@mccourtconstruction.com

Supreme Industries

Attn: Jamieson Boucher Phone: 860-485-4101

Email: dcedrone@mccourtconstruction.com

GZA

Attn: Lucas Turcotte Phone: 603-380-5017

Email: lucas.turcotte@gza.com

Environmental Consultant

Normandeau Associates, Inc.

Attn: Matt Smith-Environmental Monitor

Phone: 228-224-0098

Email: msmith@normandeau.com

Attn: Brian Emlaw - Environmental Monitor

Phone: 315-250-2525

Email: bemlaw@normandeu.com

Attn: Marc Jacobs-CPESC, NHCWS

Phone: 603-534-7645

Email: jaconbs2wetsoil2004@yahoo.com

Attn: Sarah Allen-Principal Wetland

Scientist

Phone: 603-714-3085

Email: sallen@normandeau.com