Reed & Reed, Inc.

PO Box 370 Woolwich, ME 04579 Ph: (207)443-9747

Letter of Transmittal

	ES - Water Division Date: 7/2/2019 Sox 95 Job: 532 Antrim Wind Project azen Drive					
WE ARE SENDING YOU	✓ Attache	ed	Under sepa	parate cover via None the following items:		
☐ Shop drawings	☐ Prints		☐ Plans	☐ Samples		
Copy of letter	☐ Change	☐ Change order		tions		
Document Type	Copies	Date	No.	Description		
	0	7/2/19		Box Culvert Spring Monitoring Report		
☐ For approval ☐ For your use ☐ As requested ☐ For review and commen ☐ FOR BIDS DUE Remarks: Copy To: Jeff Nelson (Trans		Approved as noted Submit copies for distribution Returned for corrections Return corrected prints Other PRINTS RETURNED AFTER LOAN TO US				
From: Dustin Littlefield (Ree	d & Reed, Inc.)	Signa	nature:		

Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

In follow-up to the restoration of the streambed at SD-4 box culvert, DES requested monitoring throughout the Spring of 2019. In addition to the 3rd Party SWPPP Inspections conducted for the whole site which encompassed the box culvert, Sargent Corporation specifically monitored the box culvert, documenting its condition and stability with weekly photos and comments. The box culvert performed well, and the streambed has returned to a natural appearance. Photos and comments from the Spring 2019 monitoring are below.

March 15, 2019:

Tim Blais: Snow covered, no visible flow but can hear water running.



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

March 20, 2019

Tim Blais: No changes this week. Can here water running under ice and snow. Water visible in stream 50' downstream from bridge in the woods. Water flowing in stream bed is clear.





Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

March 27, 2019

Mark Wright: water is clear.



April 2, 2019:

Mark Wright: Water is clear, still frozen under bridge.



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

April 10, 2019:

Mark Wright: Water running clear. Lower third of bridge still frozen.



April 16, 2019:

Mark Wright: Water clear. Ice almost gone. No scour.



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

April 23, 2019:



April 25, 2019:



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

May 1, 2019:

Mark Wright: Stream bed looks natural.



May 7, 2019:



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

May 14, 2019:

Mark Wright: Water is running clear. Stream looking natural after 1/2-inch rainstorm.



May 20, 2019:

Mark Wright: Bridge 4 is stable.



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

May 28, 2019:

Mark Wright: The grass is starting to grow.



June 6, 2019:

Mark Wright: Almost 2 inches of rain overnight.



Spring 2019 Monitoring of SD-4 Box Culvert

Updated 6/28/2019

June 25, 2019:



Next pages:

Supplemental actions undertaken June 27, 2019 in response to comments by DES in e-mail of June 24, 2019.

PROJECT:	Antrim Wind Park	DATE:	6-27-19
JOB NO:	37403	WEATHER:	Sunny
CLIENT:	Reed & Reed	TEMPERATURE:	80°F
CONTRACTOR:	Sargent Corporation	WIND:	5mph
PROJ. MANAGER:	Kevin Burns	PRECIPITATION:	

CONSTRUCTION REPORT

GENERAL CONTRACTOR PRESENT

Name of Contractor		Personnel			
⊠ Reed & Reed					
SUBCONTRACTORS PRESENT					
Time	Name / Represer				
Q.A. FIELD PERSONNEL PRESENT					
Name / Representing		Rem arks			
☐ Jason Millett, Sargent Corporation.					
REGULATORY AGENCY PERSONNEL					
Time	Name / Represer	nting Remarks			

CONSTRUCTION ACTIVITIES:

Sargent Corporation conducted the following:

- Cleaned up gravel from above the headwalls
- Pulled back slopes above headwall and stabilized to prevent gravel or any material from falling into stream
- Added large boulders to stabilize road and slope on outlet side above the headwall to avoid any future issues
- Removed stump grindings from headwall and outlet slope to ensure none fall into stream

By: Jason Millett Page 1 of 1

ANTRIM WIND PROJECT ANTRIM, NEW HAMPSHIRE



Photo No. 1

Photo Date: June 27, 2019

Site Location: Box Culvert Inlet, Antrim Wind Park, NH

Description:
Cleaned up lose
gravel and
compacted along

compacted along headwall/deck of box culvert.

Photo By: JMM



Photo No. 2

Photo Date: June 27, 2019

Site Location: Box Culvert Inlet, Antrim Wind Park, NH

Description: Pulled back top of slope and filled in voids around boulders with smaller rip rap to avoid any erosion.

Photo By: JMM

JM: 37403 PAGE 1

ANTRIM WIND PROJECT ANTRIM, NEW HAMPSHIRE



Photo No. 3

Photo Date: June 27, 2019

Site Location: Box Culvert Outlet, Antrim Wind Park, NH

Description: Placed large boulders to stabilize slope and roadway and pulled top of slope back above headwall and compacted gravel and smaller rip rap.

Photo By: JMM



Photo No. 4

Photo Date: June 27, 2019

Site Location: Box Culvert Outlet, Antrim Wind Park, NH

Description:

Cleaned up stump grindings and lose material above headwall and slope around boulders that had potential of falling into stream

Photo By: JMM

JM: 37403 PAGE 2





