

# CONSTRUCTION MONITORING REPORT

ΕV	FD	S	11	D/		F
	ᄗ	$\supset$	-0	L/I	_	

			Eversource Transmission Lines:
TYPE OF INSPECTION:Weekly	X Storm Event	Incident Corrective Action	<u>F107</u>
Date: <u>06/21/19</u> Time: <u>12:00pm</u> Was to If yes, how did you determine whether a 0.25" storm event information is from Pease Air Force Enterthyles the storm event information (approx.):	rm event has occurred? _		Madbury, Durham, Newgington, Portsmouth, NH  Alteration of Terrain Permit: SEC Docket No. 2015-004  Environmental Permit: SEC Docket No. 2015-004  USEPA NOI Tracking No: NHR1000QN NHR1000QT NHR1000QO NHR1000S6
Inspector name(s), title(s) and qualifications. Inspector and Marc Jacobs, CPESC, NHO Others present/qualifications(s): Sam Ea Weather conditions (since last inspection): F into today with sporadic light showers (6) Weather conditions (time of inspection & future with scattered clouds forecasted for the r cloudy/clear until the beginning of next with	ews ames, Eversource con Rain event beginning -21-19), with temperat are outlook): Raining of test of the day. Future	Struction representative  Thursday 6-20-19 continuing cures in the 60s and 70's.  during the time of inspection e forecast is partly	NAI Project No: 23840.39
CONSTRUCTION SITE SEQUENCING Disturbed area and ongoing work (acreage of the proceeding per approved plan?  Operating within phasing limitations?  X Y	& description): < 1 acre  'esNo, if not,		

## Eversource Seacoast Reliability Project

#### PROJECT TEAM

Eversource

Attn: Dena Champy-Eversource Project Manager

Phone: 603-634-2891

Email: Dena.champy@eversource.com

Attn: Tom Sullivan- Construction Mgmt

Phone: 978-502-3805

Email: Thomas.sullivan@eversource.com

Attn: Joseph Sperry- Eversource Senior Engineer

Phone: 603-634-2562

Email: joseph.sperry@eversource.com

Attn: Kurt Nelson- Eversource Permittingr

Phone: 603-714-3031

Email: hurt.nelson@eversource.com

Attn: Lauren Cote- Municipal Outreach

Phone: 603-634-2409

Email: lauren.cote@eversource.com

Attn: Sam Eames- Construction Rep

Phone: 603-915-0073

Email: samuel.eames@eversource.com

Attn: Thomas Meister- Construction Rep

Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Joshua Scott-ROW Safety Mgr

Phone: 603-848-7759

Email: joshua.scott@eversource.com

Cotractors

JCR Utility Construction Co. Inc.

Attn: Matt Moreau- Project Manager

Phone: 603-895-4062

Email: Matt.moreau@jcrutility.com

Dan Jarry- Superintendent

Phone: 603-238-5523

Email: Daniel.jarry@jcrutility.com

McCourt Construction

Attn: Micheal Worhunsky- Project Manager

Phone: 617-293-3864

Email: Mworhunsky@mccourtconstruction.com

Attn: Scott Gorman-Safety Director

Phone: 617-828-8822

Email: SGorman@mccourtconstruction.com

Attn: Dan Cedrone- Superintendant

Phone: 617-908-2660

Email: dcedrone@mccourtconstruction.com

Supreme Industries

Attn: Jamieson Boucher Phone: 860-485-4101

Email: jboucher@supremeindustries.com

**GZA** 

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: lucas.turcotte@gza.com

**Environmental Consultant** 

Normandeau Associates, Inc.

Attn: Matt Smith- Environmental Monitor

Phone: 228-224-0098

Email: msmith@normandeau.com

Attn: Brian Emlaw- Environmental Monitor

Phone: 315-250-2525

Email: bemlaw@normandeau.com

Attn: Cassandra O'Brien- Environmental Monitor

Phone: 603-969-1175

Email: cobrien@normandeau.com

Attn: Marc Jacobs - CPESC, NHCWS

Phone: 603-534-7645

Email: jacobs2wetsoil2004@yahoo.com

Attn: Sarah Allen- Principal Wetland Scientist

Phone: 603-714-3085

Email: sallen@normandeau.com

#### **General Comments**

Exposed soil was observed next to Str. F107-136 due to utility work along Woodbury Ave.

#### Work completed this week:

- Portsmouth
  - o Boulos continues to do work at substation.
- Newington
  - o None
- Durham
  - o McCourt continues to excavate, fuse pipe, assemble conduit and assembling duct bank in "A" lot.
  - o McCourt finished hammering ledge next to the field house.
  - McCourt began excavating for duct bank next to the field house at UNH. Soil is stockpiled in the Waterworks Rd laydown area.
  - McCourt finished excavating for the jacking pit.
  - o Maine drilling and blasting finished their blasting activities.
  - o GZA continues to manage soil stockpile area in "A" lot.
  - o Soil is being hauled out of "A" lot as well as Waterworks Rd laydown area.
  - Midwest Mole is onsite prepping for drilling activities in jacking pit.
  - o Supreme Inc. began tree clearing at Gundalow landing. On hold for now.

#### Erosion and sediment control items and observations:

• The soil in the Waterworks Rd laydown was stockpiled slightly beyond the straw wattles that they had in place. McCourt was instructed to install silt fence around any soil stockpiles.

#### BMPs

- McCourt installed a silt fence on the north side of the Waterworks Rd laydown yard, between the soil stockpile and wetland DW65. This protected the wetland from any soil runoff from the laydown area. McCourt was instructed to key the silt fence into the ground, leaving no space between the fence and the ground surface. (This maintenance was completed 6-20-19).
- The contractors have been reminded that they need to have spare BMP supplies on hand in case of emergencies. These spare supplies should be kept dry at all times; this is a requirement of the BMPs, Eversource and DES.

#### **Corrective Action**

None needed.



Fig 1: GZA continues to haul out soil from stockpile area in "A" lot. Viewing north. (6-20-19).



Fig 3: Silt sock installed along trenching activities in "A" lot. Viewing south. (6-21-19).



Fig 2: Vac truck is used to pump rain water out of trench in "A" lot. Viewing south. (6-20-19).



Fig 4: Trenching for duct bank next to field house at UNH. Viewing south. (6-21-19).



Fig 5: Silt fence and straw wattle installed between soil stockpiled in Waterworks Rd lay down area and wetland DW65. Viewing east. (6-21-19).



Fig 7: Combined berm installed correctly in lay down area off of Gosling Rd. Viewing south. (6-20-19).



Fig 6: Silt fence and straw wattle installed between soil stockpiled in Waterworks Rd lay down area and wetland DW65. Viewing east. (6-21-19).



Fig 8: Combined berm installed correctly in lay down area off of. Gosling Rd. Viewing north. (6-20-19).



Fig 9: Combined berm installed correctly in lay down area off of Gosling Rd. Viewing east. (6-20-19).



Fig 11: Silt fence and straw bales installed in low lying area between Str. F107-137 and wetland NW37. Viewing northeast. (6-21-19).



Fig 10: Str. F107-137 foundation and work pad seeded and broadcast with straw, grass beginning to grow. Viewing northeast. (6-20-19).



Fig 12: Exposed soil next to Str. F107-136 due to utility work along Woodbury Ave. Viewing southwest. (6-21-19).



Fig 13: Str. F107-135 foundation and work site. Straw wattle are installed correctly and area has been seeded and broadcast with straw. Viewing southwest. (6-21-19).



Fig 14: Str. F107-135 foundation in Newington mall parking lot, note germination. Viewing northeast. (6-21-19).

## Construction Monitoring Report #9

۲	F	R	т	IF	IC	`Δ	ıΤ	1	1	Ν	ı

earling the transfer of the tr					
OPERATING WITHIN LIMITS? N/A X_YESNO if not, please explain:					
SURFACE WATER QUALITY					
Storm water discharge from the site at the time of inspection?  Storm water discharge consistent with water quality standards?  Turbidity visually observed?  If yes, check appropriate location(s) below, and describe discharge:  X YES  NO  N/A  YES  NO  N/A  NO					
Location: Pond location: N/A Adjacent surface water or wetland:					
Description:					
TEMPORARY EROSION AND SEDIMENT CONTROLS (TESC)					
Installed and functioning per the SWPPP? X_YESNON/A (See erosion control installation/repair items above)					
Are any corrective actions required?YESX_NO if so, please describe?					
* Note: The permit differentiates between conditions requiring repairs and maintenance, and those requiring corrective action. Corrective actions are triggered only for specific, more serious conditions and require a corrective action form be filled out. Please refer to Part 5 of the CGP for additional information					
PERMANENT EROSION AND SEDIMENTATION CONTROLS (PESC)					
Disturbed areas must have a uniform perennial vegetative cover with 85% density, or equivalent physical stabilization, to be considered permanently stabilized (per the SWPPP).					
Installed and functioning per the SWPPP? X_YESNON/A					
If not, explain what was not performed correctly (construction/stabilization) for each of the following categories. Detail what/where needs to be corrected, and what has been corrected since the last monitoring inspection.					
If so, what areas: Structures. F107-134, 135 and 137 have germination.					
Storm Water Conveyance, Soil Stabilization, and Storm Water Treatment, Other:					
OTHER COMMENTS AND OBSERVATIONS:					
-None other than the above comments.					
"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."					
This form is completed and signed in accordance with the Signatory Requirements specified in Appendix I.11 of the NPDES CGP for the project site and NOI identified above.					
Authorized signature: MARC F_JACOBS Date: 6/21/19					

8