

Date:

NOTE:

TYPE OF INSPECTION:

+Storm event information (approx.):

Storm event information is from Pease Air Force Base.

CONSTRUCTION MONITORING REPORT

04/10/20 Time: 8:00am 'Does this report include a 0.25" storm event? X Yes No If yes, how did you determine whether a 0.25" storm event has occurred? ___Rain Gauge X Weather Station

Start date:

Start date:

Start date: 04-09-20

__Weekly X Storm Event __Incident __Corrective Action

Amount (inches):

Amount (inches):

Amount (inches):

0.99 in



Eversource Transmission Lines: F107

Madbury, Durham, Newington, Portsmouth, NH

Alteration of Terrain Permit: SEC Docket No. 2015-004

Environmental Permit: SEC Docket No. 2015-004

USEPA NOI Tracking No: NHR1000QN **NHR1000QT** NHR1000QO NHR1000S6

NAI Project No: 23840.39

Inspector name(s), title(s) and qualifications: Matthew Smith, Normandeau Environmental Inspector and Marc Jacobs, CPESC, NHCWS

Others present/gualifications(s): Sam Eames, Eversource construction representative

Weather conditions (since last inspection): Rain. Temperatures in the 40's.

Weather conditions (time of inspection & future outlook): Clear, temperature in the 40's. Future forecast shows clear weather throughout the weekend with rain early next week. Temperatures in the 40's and 50's.

CONSTRUCTION SITE SEQUENCING AND DISTURBANCE

Disturbed area and ongoing work (acreage & description): < 1 acre

Proceeding per ap

___No, if not, note area and explain:

Operating within phasing limitations? X Yes

___No, if not, note area and explain:

1

General Comments

- Continued BMP maintenance and upkeep is a constant priority on shorelines of both sides of the Bay during the winter months.
- Housekeeping such as sweeping of timber mats and roads is a must.
- All contractors on site should have a copy of the construction drawings.
- During mat removal be sure to remove any remains of silt socks etc.

Work completed this week:

- Portsmouth
 - No active construction during inspection.
- Newington
 - No active construction during inspection.
- Durham.
 JCR continues working on jacking and framing structures 76 and 77.

Erosion and sediment control items and observations:

- BMPs
 - o All required BMPs need to be installed as access roads are being built, before construction starts.

Corrective Action

None

OPERATING WITHIN LIMITS?
N/A XYESNO if not, please explain:
SURFACE WATER QUALITY
Storm water discharge from the site at the time of inspection? _YES _NO _N/A Storm water discharge consistent with water quality standards? _YES _NO _X_N/A Turbidity visually observed? _YES _X_NO _X_N/A If yes, check appropriate location(s) below, and describe discharge: _YES _X_NO
Location: N/A Pond location: N/A Adjacent surface water or wetland: N/A
Description: N/A.
TEMPORARY EROSION AND SEDIMENT CONTROLS (TESC)
Installed and functioning per the SWPPP? X YES NO N/A
Are any corrective actions required? <u>X</u> YESNO if so, please describe? See comments below. * Note: The permit differentiates between conditions requiring repairs and maintenance, and those requiring corrective action. Corrective actions are triggered only for specific, more serious conditions and require a corrective action form be filled out. Please refer to Part 5 of the CGP for additional information
PERMANENT EROSION AND SEDIMENTATION CONTROLS
Disturbed areas must have a uniform perennial vegetative cover with 85% density, or equivalent physical stabilization, to be considered permanently stabilized (per the SWPPP).
Installed and functioning per the SWPPP? X_YESNON/A
If not, explain what was not performed correctly (construction/stabilization) for each of the following categories. Detail what/where needs to be corrected, and what has been corrected since the last monitoring inspection. If so, what areas: N/A
Areas that have been restored and mulched, but have little germination: Both sides of Little Bay. Trench between Strs. 106- 107 (Frink farm-Hannah Lane). Strs. 28 & 29. Moderate germination: Strs. 135 – 139. Stabilized (85%+ germination): Field house at UNH, Colovos Rd at UNH, and College Brook at UNH.
OTHER COMMENTS AND OBSERVATIONS:

-None other than the above comments.

CERTIFICATION:

01

ERTIFICATION: "I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible (or gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."

This form is completed and signed in accordance with the Signatory Requirements specified in Appendix I.11 of the NPDES CGP for the project site and NOI identified above.

Authorized signature:

Date: 04/10/20



Fig 1: Wetland DW48 and Str. 28. Viewing north. (04-10-20).



Fig 2: Str. 28 foundation. Viewing east. (04-10-20).



Fig 3: Str. 57 foundation and work area. Viewing north. (04-10-20).



Fig 4: Str. 93 foundation can set and work area. Viewing east. (04-10-20).



Fig 5: Str. 94 foundation can set and work area. Viewing east. (04-10-20).



Fig 6: Previous erosion repairs are holding up on the slope at the Getchell property/west side of the Bay. Viewing east. (04-10-20).

Eversource Seacoast Reliability Project



Fig 7: BMPs at toe of slope at Getchell property/west side of the Bay. Viewing south. (04-10-20).



Fig 8: Str. 75 foundation. Viewing southeast. (04-10-20).

Eversource Seacoast Reliability Project



Fig 9: Access road over stonewall WP-28 and through wetland DW25 to Str. 76. Viewing east. (04-10-20).



Fig 10: BMPs at toe of slope, east side of the Bay. Note marine wrack trapped behind silt curtain. Straw is stable on slope. Viewing south. (04-10-20).

Eversource Seacoast Reliability Project

PROJECT TEAM

Eversource

Attn: Dena Champy-Eversource Project Manager Phone: 603-634-2891 Email: <u>dena.champy@eversource.com</u>

Attn: Tom Sullivan-Construction Management Phone: 078-502-3805 Email: thomas.sullivan@eversource.cm

Attn: Joseph Sperry-Eversource Senior Engineer Phone: 603-634-2562 Email: joseph.sperry@eversource.com

Attn: Kurt Nelson-Eversource Permitting Phone: 603-714-3031 Email: <u>kurt.nelson@eversource.com</u>

Attn: Lauren Cote-Municipal Outreach Phone: 603-634-2409 Email: <u>lauren.cote@eversource.com</u>

Attn: Sam Eames-Construction Rep Phone: 603-915-0073 Email: <u>sam.eames@eversource.com</u>

Attn: Thomas Meister-Construction Rep Phone: 339-987-7901 Email: <u>Thomas.meister@eversource.com</u>

Attn: Joshua Scott-ROW Safety Mgr Phone: 603-848-7759 Email: <u>Joshua.scott@eversource.com</u>

Contractors

<u>JCR Utility Construction Co., Inc.</u> Attn: Matt Moreau-Project Manager Phone: 603-895-4062 Email: <u>matt.moreau@crutility.com</u>

McCourt Construction Attn: Michael Worhunsky-Project Manager Phone: 617-293-3864 Email:mworhunsky@mccourtconstruction.com

Attn: Scott Gorman-Safety Director Phone: 617-828-8822 Email: <u>sqorman@mccourtconstruction.com</u>

Attn: Dan Cedrone-Superintendant Phone: 617-908-2660 Email: <u>dcedrone@mccourtconstruction.com</u>

Supreme Industries

Attn: Jamieson Boucher Phone: 860-485-4101 Email: <u>dcedrone@mccourtconstruction.com</u>

GZA

Attn: Lucas Turcotte Phone: 603-380-5017 Email: lucas.turcotte@gza.com

Environmental Consultant

Normandeau Associates, Inc. Attn: Matt Smith-Environmental Monitor Phone: 228-224-0098 Email: <u>msmith@normandeau.com</u>

Attn: Brian Emlaw – Environmental Monitor Phone: 315-250-2525 Email: <u>bemlaw@normandeu.com</u>

Attn: Marc Jacobs-CPESC, NHCWS Phone: 603-534-7645 Email: jaconbs2wetsoil2004@yahoo.com

Attn: Sarah Allen-Principal Wetland Scientist Phone: 603-714-3085 Email: <u>sallen@normandeau.com</u>