

DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

 TYPE OF INSPECTION:
 Daily
 Weekly
 Storm Event*
 Reduced Frequency**

 Other:
 Other:

 Date:
 7/23/2020
 Time:
 1340
 *Was this inspection triggered by a 0.25" storm event?
 Yes
 No

 If yes, how did you determine whether a 0.25" storm event has occurred?
 Rain Gauge
 Weather Station

 Ø Other
 If other, please describe Weather Underground
 +Storm event info (approx): Rain late on 7/22 and into early morning of 7/23

 Amount of rainfall (inches):
 0.50
 ++Reason for Reduced Frequency (*i.e., Monthly due to dry conditions*):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Mostly dry, no measurable precipitation

Weather conditions (time of inspection): Overcast/Some Light Rain, Mid 80's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: **7/23/20** Time: **1335** Notes:

PROJECT TEAM

PROJEC	TOWNER	ENVIRO	NMENTAL CONSULTANT		
Eversour	ce	GZA GeoEnvironmental, Inc.			
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier		
Phone:	508-954-2736	Phone:	603-380-5024		
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com		
A					
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox		
Phone:	603-714-3031	Phone:	603-315-7520		
Email:	kurt.nelson@eversource.com	Email:	rebecca.cox@gza.com		
Attn:	Tom Meister	Attn:	Lucas Turcotte		
Phone:	339-987-7901	Phone:	603-380-5017		
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com		
Attn:	Sam Eames				
Phone:	603-915-0073				
Email:	samual eames@eversource.com				
EVERSO	URCE COMPLIANCE				
Attn:	Matt Cardin				
Phone:	603-988-6635				
Email:	matthew.cardin@eversource.com				
FIELD SE	RVICES SAFETY MANAGER				
Transmis	ssion ROW				
Attn:	Joshua Scott				
Phone:	603-848-7759				
Email:	Joshua.scott@eversource.com				

Eversource Transmission Line:

> F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No: 04.0190967.00

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

Sod and loam/seed recently applied around drainage area. Watered periodically. No watering occurring at time of inspection. ٠



29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



29 Gundalow -1 (Drainage Area)



64 Gundalow – 2 (Drainage Course)



4 Brickyard Circle – 1 (Drainage Course)

Page 3 of 4

DRAINAGE AREA MONITORING			
Location: 29 Gundalow – 1 (Drainage Area) Status of surface water at the time of inspection?	🗌 Dry	Standing	Flowing
pH: Not Monitored – Could not access due to sta	aked hay	bale	
Observations/Notes:			
Location: 29 Gundalow – 2 (Culvert) Status of surface water at the time of inspection?	🗌 Dry	Standing	Flowing
pH: 8.4			
Observations/Notes: ~ 4" of standing water in culver	t		
Location: 64 Gundalow – 1 (Drainage Course) Status of surface water at the time of inspection? pH:	🛛 Dry	Standing	Flowing
Observations/Notes:			
Location: 64 Gundalow – 2 (Drainage Course) Status of surface water at the time of inspection? pH: 7.0	🗌 Dry	Standing	Flowing
Observations/Notes: Small area of standing water a	adjacent to	o culvert inlet, a	approx. 1" deep
Location: 4 Brickyard Circle – 1 (Drainage Cours Status of surface water at the time of inspection?	se) Dry	Standing	Flowing
pH: 7.0			
Observations/Notes: ~ 8" of standing water extending	ıg ~ 12" b	eyond culvert o	outlet in grassed raceway
Location: Knight's Brook – 1 (Upstream in Broo Status of surface water at the time of inspection?	k) □ Dry	Standing	□ Flowing
pH: Not Monitored			
Observations/Notes:			
Location: Knight's Brook – 2 (Downstream in Br Status of surface water at the time of inspection? pH: Not Monitored	_ `	Standing	Flowing
Observations/Notes:			
Location: Knight's Brook – 3 (Above Duct Bank Status of surface water at the time of inspection? pH: Not Monitored) Standing	Flowing
Observations/Notes:			
Location: Hannah – 1 (Wetland NW-22) Status of surface water at the time of inspection? pH: Not Monitored	🗌 Dry	Standing	Flowing
Observations/Notes:			

Eversource Energy Seacoast Reliability Project Project #04.0190967.00

Page 4 of 4

Location: Hannah – 2 (Wetland NW-24) Status of surface water at the time of inspection?	🗌 Dry	Standing	Flowing
pH: Not Monitored			
Observations/Notes:			
Location: Flynn Pit – 1 (Wetland NW-4) Status of surface water at the time of inspection? pH: Not Monitored	🗌 Dry	Standing	Flowing
Observations/Notes:			
Location: Status of surface water at the time of inspection? pH:	🗌 Dry	Standing	☐ Flowing
Observations/Notes:			

OTHER COMMENTS AND OBSERVATIONS

None