



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION: Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **8/4/20** Time: **1830** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe

+Storm event info (approx): Variable rain and strong wind evening of 8/4

Amount of rainfall (inches): 0.09

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Rebecca Cox, P.E.

Others present/affiliation(s):

Weather conditions (since last inspection): Mostly sunny, no measurable precipitation

Weather conditions (time of inspection): Rain and Wind, Low 70's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point
Date: **8/4/20** Time: **1825**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager
Phone: 508-954-2736
Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Tom Meister
Phone: 339-987-7901
Email: thomas.meister@eversource.com

Attn: Sam Eames
Phone: 603-915-0073
Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin
Phone: 603-988-6635
Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott
Phone: 603-848-7759
Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier
Phone: 603-380-5024
Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox
Phone: 603-315-7520
Email: rebecca.cox@gza.com

Attn: Lucas Turcotte
Phone: 603-380-5017
Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- Sod and loam/seed recently applied around drainage area. Watered periodically. No watering occurring at time of inspection.

PHOTOGRAPHS



29 Gundalow -1 (Drainage Area)



29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes: Bottom of culvert observed moist but not sufficient water to measure pH.

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.4

Observations/Notes: Small area of standing water adjacent to culvert inlet, approx. 1" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.9

Observations/Notes: ~ 8" of standing water extending ~ 12" beyond culvert outlet in grassed raceway

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- None



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION:

- Daily
 Weekly
 Storm Event⁺
 Reduced Frequency⁺⁺
 Other:

Date: **8/5/2020** Time: **0930** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency (i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Mostly cloudy and windy to fair

Weather conditions (time of inspection): Sunny, High 70's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point

Date: **8/5/20** Time: **0925**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager
Phone: 508-954-2736
Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Tom Meister
Phone: 339-987-7901
Email: thomas.meister@eversource.com

Attn: Sam Eames
Phone: 603-915-0073
Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin
Phone: 603-988-6635
Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott
Phone: 603-848-7759
Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier
Phone: 603-380-5024
Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox
Phone: 603-315-7520
Email: rebecca.cox@gza.com

Attn: Lucas Turcotte
Phone: 603-380-5017
Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- Sod and loam/seed recently applied around drainage area. Watered periodically. No watering occurring at time of inspection.

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes: Bottom of culvert observed to be moist but not sufficient water to measure pH

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **6.6**

Observations/Notes: Small area of standing water adjacent to culvert inlet, approx. 1" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **7.1**

Observations/Notes: ~ 8" of standing water extending ~ 12" beyond culvert outlet in grassed raceway

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- None



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION:

- Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **8/7/2020** Time: **1030** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Mostly cloudy and windy to fair

Weather conditions (time of inspection): Sunny, High 70's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point

Date: **8/7/20** Time: **1025**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager
Phone: 508-954-2736
Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Tom Meister
Phone: 339-987-7901
Email: thomas.meister@eversource.com

Attn: Sam Eames
Phone: 603-915-0073
Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin
Phone: 603-988-6635
Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott
Phone: 603-848-7759
Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier
Phone: 603-380-5024
Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox
Phone: 603-315-7520
Email: rebecca.cox@gza.com

Attn: Lucas Turcotte
Phone: 603-380-5017
Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- Sod and loam/seed recently applied around drainage area. Watering occurring at time of inspection.

PHOTOGRAPHS



29 Gundalow -1 (Drainage Area)



29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes: Bottom of culvert observed to be moist but not sufficient water to measure pH

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **6.6**

Observations/Notes: Small area of standing water adjacent to culvert inlet, approx. 1" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **7.3**

Observations/Notes: ~ 8" of standing water extending ~ 12" beyond culvert outlet in grassed raceway

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- Watering occurring in the vicinity of 64 Gundalow – 1 at time of inspection.