

# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

TYPE OF INSPECTION:	Daily Weekly Storm Event <sup>+</sup> Reduced Frequency <sup>++</sup>
	Other:
Date: 8/17/2020 Time: 10	<b>05</b> <sup>+</sup> Was this inspection triggered by a 0.25" storm event? $\Box$ Yes $\boxtimes$ No
If yes, how did you determine w Other If other, please des +Storm event info (approx): Lig	5
Amount of rainfall (inches): 0.04	<b>.</b>
++Reason for Reduced Freque ( <i>i.e., Monthly due to dry conditi</i>	

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Fair to cloudy, some overnight precipitation 8/16 to 8/17

Weather conditions (time of inspection): Mostly cloudy, Low 70's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: **8/17/20** Time: **0915** Notes:

#### **PROJECT TEAM**

PROJEC	TOWNER	ENVIRO	MENTAL CONSULTANT
Eversour	ce	GZA Geo	Environmental, Inc.
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier
Phone:	508-954-2736	Phone:	603-380-5024
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox
Phone:	603-714-3031	Phone:	603-315-7520
Email:	kurt.nelson@eversource.com	Email:	<u>rebecca.cox@gza.com</u>
Attn:	Tom Meister	Attn:	Lucas Turcotte
Phone:	339-987-7901	Phone:	603-380-5017
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com
Attn:	Sam Eames		
Phone:	603-915-0073		
Email:	samual eames@eversource.com		
EVERSO	URCE COMPLIANCE		
Attn:	Matt Cardin		
Phone:	603-988-6635		
Email:	matthew.cardin@eversource.com		
Email.	mattrew.eardineeversource.com		
FIELD SE	RVICES SAFETY MANAGER		
	ssion ROW		
Attn:	Joshua Scott		
Phone:	603-848-7759		
Email:	Joshua.scott@eversource.com		

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Durham, New Hampshire

GZA Project No: 04.0190967.00

## CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

• Portions of Waterworks Road and Colovos Road adjacent to monitoring sites recently re-paved.

# PHOTOGRAPHS



UNH Wetland - 1 (Stormwater Area)



UNH Wetland - 3 (Cattail Wetland)



UNH Wetland - 5 (Cattail Wetland)



UNH Wetland – 2 (Stormwater Area)



UNH Wetland - 4 (Cattail Wetland)



UNH Wetland - 6 (Cattail Wetland)

DRAINAGE AREA MONITORING
Location: UNH Wetland – 1 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 2 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 3 (Cattail Wetland) Status of surface water at the time of inspection?  Dry Standing Flowing pH: Observations/Notes:
Location: UNH Wetland – 4 (Cattail Wetland) Status of surface water at the time of inspection?  Dry  Standing  Flowing pH:
Observations/Notes:
Location: UNH Wetland – 5 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 6 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: College Brook – 1 (Upstream in Brook)
Status of surface water at the time of inspection?  Dry  Standing  Flowing
pH: Not Monitored
Observations/Notes:
Location: College Brook – 2 (Downstream in Brook)         Status of surface water at the time of inspection?       Dry       Standing       Flowing         pH: Not Monitored       Observations/Notes:       Standing       Flowing

Eversource Energy Seacoast Reliability Project Project #04.0190967.00

Location: CB – 1 (Catch Basin) Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: CB – 2 (Catch Basin))			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: RG – 1 (Rain Garden)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: A Lot – 1 (Drainage Swale)			
Status of surface water at the time of inspection?	□ Drv	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: Reservoir Brook – 1 (Brook)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location:			
Status of surface water at the time of inspection?	∐ Dry	Standing	
pH:			
Observations/Notes:			

### OTHER COMMENTS AND OBSERVATIONS

• All monitored locations dry at time of inspection.



# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

 TYPE OF INSPECTION:
 Daily
 Weekly
 Storm Event<sup>+</sup>
 Reduced Frequency<sup>++</sup>

☐ Other: Date: 8/18/2020 Time: 1005 <sup>+</sup>Was this inspection triggered by a 0.25" storm event? ☐ Yes ⊠ No If yes, how did you determine whether a 0.25" storm event has occurred? ☐ Rain Gauge ☐ Weather Station ☐ Other If other, please describe Weather Underground +Storm event info (approx): Light rain early morning of 8/18 Amount of rainfall (inches): 0.17 ++Reason for Reduced Frequency

(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Fair to cloudy, light precipitation early morning of 8/18

Weather conditions (time of inspection): Partly cloudy, Low 70's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: **8/18/20** Time: **0920** Notes:

#### **PROJECT TEAM**

PROJEC	Γ OWNER	ENVIRO	MENTAL CONSULTANT
Eversourc	e	GZA Geo	Environmental, Inc.
Attn:	 Dena Champy-Project Manager	Attn:	Deborah Zarta Gier
Phone:	508-954-2736	Phone:	603-380-5024
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox
Phone:	603-714-3031	Phone:	603-315-7520
Email:	kurt.nelson@eversource.com	Email:	<u>rebecca.cox@gza.com</u>
		• • •	
Attn:	Tom Meister	Attn:	Lucas Turcotte
Phone:	339-987-7901	Phone:	603-380-5017
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com
Attn:	Sam Eames		
Phone:	603-915-0073		
Email:	samual eames@eversource.com		
Linaii.	Samual cames @ eversource.com		
EVERSO	JRCE COMPLIANCE		
Attn:	Matt Cardin		
Phone:	603-988-6635		
Email:	matthew.cardin@eversource.com		
FIELD SE	RVICES SAFETY MANAGER		
	sion ROW		
Attn:	Joshua Scott		
Phone:	603-848-7759		
Email:	Joshua.scott@eversource.com		

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Durham, New Hampshire

GZA Project No: 04.0190967.00

## CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

• Portions of Waterworks Road and Colovos Road adjacent to monitoring sites recently re-paved.

# PHOTOGRAPHS



UNH Wetland - 1 (Stormwater Area)



UNH Wetland - 3 (Cattail Wetland)



UNH Wetland - 5 (Cattail Wetland)



UNH Wetland – 2 (Stormwater Area)



UNH Wetland - 4 (Cattail Wetland)



UNH Wetland - 6 (Cattail Wetland)

DRAINAGE AREA MONITORING
Location: UNH Wetland – 1 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 2 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 3 (Cattail Wetland) Status of surface water at the time of inspection?  Dry Standing Flowing pH: Observations/Notes:
Location: UNH Wetland – 4 (Cattail Wetland) Status of surface water at the time of inspection?  Dry  Standing  Flowing pH:
Observations/Notes:
Location: UNH Wetland – 5 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 6 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: College Brook – 1 (Upstream in Brook)
Status of surface water at the time of inspection?  Dry  Standing  Flowing
pH: Not Monitored
Observations/Notes:
Location: College Brook – 2 (Downstream in Brook)         Status of surface water at the time of inspection?       Dry       Standing       Flowing         pH: Not Monitored       Observations/Notes:       Standing       Flowing

Eversource Energy Seacoast Reliability Project Project #04.0190967.00

Location: CB – 1 (Catch Basin) Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: CB – 2 (Catch Basin))			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: RG – 1 (Rain Garden)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: A Lot – 1 (Drainage Swale)			
Status of surface water at the time of inspection?	□ Drv	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: Reservoir Brook – 1 (Brook)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location:			
Status of surface water at the time of inspection?	∐ Dry	Standing	
pH:			
Observations/Notes:			

### OTHER COMMENTS AND OBSERVATIONS

• All monitored locations dry at time of inspection.



# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

<b>TYPE OF INSPECTION:</b> Daily Weekly Storm Event <sup>+</sup> Reduced Frequency <sup>++</sup>
☐ Other:
Date: 8/202020 Time: 0845 <sup>+</sup> Was this inspection triggered by a 0.25" storm event? 🛛 Yes 🗌 No
If yes, how did you determine whether a 0.25" storm event has occurred?  Rain Gauge  Weather Station Gother If other, please describe Weather Underground
+Storm event info (approx): Variable rain/thunderstorms evening of 8/19
Amount of rainfall (inches): 0.41
++Reason for Reduced Frequency ( <i>i.e., Monthly due to dry conditions</i> ):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Fair to cloudy, Variable rain/thunderstorms evening of 8/19

Weather conditions (time of inspection): Partly cloudy, Mid 60's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: **8/20/20** Time: **0805** Notes:

#### **PROJECT TEAM**

PROJEC	TOWNER	ENVIRO	MENTAL CONSULTANT
Eversour	-	-	Environmental, Inc.
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier
Phone:	508-954-2736	Phone:	603-380-5024
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com
			5 5
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox
Phone:	603-714-3031	Phone:	603-315-7520
Email:	kurt.nelson@eversource.com	Email:	rebecca.cox@gza.com
			-
Attn:	Tom Meister	Attn:	Lucas Turcotte
Phone:	339-987-7901	Phone:	603-380-5017
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com
Attn:	Sam Eames		
Phone:	603-915-0073		
Email:	samual eames@eversource.com		
EVERSO	URCE COMPLIANCE		
Attn:	Matt Cardin		
Phone:	603-988-6635		
Email:	matthew.cardin@eversource.com		
Linaii.	matthew.cardineeversource.com		
	ERVICES SAFETY MANAGER asion ROW		
Attn:	Joshua Scott		
Phone:	603-848-7759		
Email:	Joshua.scott@eversource.com		
Linali.	0031108.30011@6761300106.0011		
L		I	

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Durham, New Hampshire

GZA Project No: 04.0190967.00

## CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

• Portions of Waterworks Road and Colovos Road adjacent to monitoring sites recently re-paved.

## PHOTOGRAPHS



UNH Wetland - 1 (Stormwater Area)



UNH Wetland - 3 (Cattail Wetland)



UNH Wetland - 5 (Cattail Wetland)



UNH Wetland – 2 (Stormwater Area)



UNH Wetland - 4 (Cattail Wetland)



UNH Wetland - 6 (Cattail Wetland)

DRAINAGE AREA MONITORING
Location: UNH Wetland – 1 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 2 (Stormwater Area)         Status of surface water at the time of inspection?       Image: Dry i
Observations/Notes: Some very small pockets of standing water ~ 0.25" deep, not enough to sample
Location: UNH Wetland – 3 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 4 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 5 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: UNH Wetland – 6 (Cattail Wetland)         Status of surface water at the time of inspection?       Image: Dry i
Location: College Brook – 1 (Upstream in Brook)         Status of surface water at the time of inspection?       Dry       Standing       Flowing         pH: Not Monitored         Observations/Notes:
Location: College Brook – 2 (Downstream in Brook)         Status of surface water at the time of inspection?       Dry         Standing       Flowing         pH: Not Monitored       Observations/Notes:

Eversource Energy Seacoast Reliability Project Project #04.0190967.00

Location: CB – 1 (Catch Basin) Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: CB – 2 (Catch Basin))			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: RG – 1 (Rain Garden)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: A Lot – 1 (Drainage Swale)			
Status of surface water at the time of inspection?	□ Drv	Standing	
pH: Not Monitored			
Observations/Notes:			
Location: Reservoir Brook – 1 (Brook)			
Status of surface water at the time of inspection?	🗌 Dry	Standing	
pH: Not Monitored			
Observations/Notes:			
Location:			
Status of surface water at the time of inspection?	∐ Dry	Standing	
pH:			
Observations/Notes:			

### OTHER COMMENTS AND OBSERVATIONS

• All monitored locations dry at time of inspection.