



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION: Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **09/22/2020** Time: **1210** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds, no measurable precipitation

Weather conditions (time of inspection): Partly Cloudy, Mid 60's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point

Date: **9/22/20** Time: **1205**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: kurt.nelson@eversource.com

Attn: Tom Meister

Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Sam Eames

Phone: 603-915-0073

Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox

Phone: 603-315-7520

Email: rebecca.cox@gza.com

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- None

PHOTOGRAPHS



29 Gundalow -1 (Drainage Area)



29 Gundalow -2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: Visible moisture on inside of culvert but no standing water

Observations/Notes:

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes: Very small, shallow pocket of water remaining but not sufficient to achieve pH reading

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes: Moisture at culvert outlet but no standing water

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- 64 Gundalow – 2 location was dry for the first time since the June 29, 2020 monitoring event. This is the first time that all Newington monitoring locations have been dry since monitoring began on June 5, 2020.