



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION: Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **10/13/2020** Time: **1350** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe Weather Underground

+Storm event info (approx): Variable, steady rain from early morning to evening of 10/13

Amount of rainfall (inches): Approx. 1.2 at time of inspection, 1.5 total

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds with variable, steady rain from early morning to evening of 10/13

Weather conditions (time of inspection): Rain, Low 50's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **10/13/20** Time: **1345**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: kurt.nelson@eversource.com

Attn: Tom Meister

Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Sam Eames

Phone: 603-915-0073

Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox

Phone: 603-315-7520

Email: rebecca.cox@gza.com

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- None

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: Visible moisture on inside of culvert but no standing water

Observations/Notes:

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.4

Observations/Notes: Standing water extending approx. 16" from culvert inlet into stone riprap area, standing water approx. 4" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.5

Observations/Notes: Standing water extending approx. 18" beyond culvert outlet, approx. 10" deep

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- None



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION: Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **10/14/2020** Time: **1005** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe Weather Underground

+Storm event info (approx): Variable, steady rain from early morning to evening of 10/13

Amount of rainfall (inches): 1.5

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Steady rain from early morning to evening of 10/13, Mostly sunny 10/14

Weather conditions (time of inspection): Sunny, Low 60's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **10/14/20** Time: **1000**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: kurt.nelson@eversource.com

Attn: Tom Meister

Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Sam Eames

Phone: 603-915-0073

Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox

Phone: 603-315-7520

Email: rebecca.cox@gza.com

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- None

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 10.2

Observations/Notes: Standing water observed in the culvert and extending approx. 10" beyond culvert inlet into stone area, approx. max depth 3.5"

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.3

Observations/Notes: Standing water extending approx. 12" from culvert inlet into stone riprap area, standing water approx. 3" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.5

Observations/Notes: Standing water extending approx. 16" beyond culvert outlet, approx. 8" deep

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- Standing water present in 29 Gundalow – 2 for the first time since the July 23rd monitoring event. No flow through culvert observed.



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION:

- Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **10/16/2020** Time: **1410** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches): 0.2 at time of inspection

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Cloudy to fair on 10/15, variable rain from late morning into afternoon of 10/16

Weather conditions (time of inspection): Cloudy, Low 60's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **10/16/20** Time: **1405**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager
Phone: 508-954-2736
Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Tom Meister
Phone: 339-987-7901
Email: thomas.meister@eversource.com

Attn: Sam Eames
Phone: 603-915-0073
Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin
Phone: 603-988-6635
Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott
Phone: 603-848-7759
Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier
Phone: 603-380-5024
Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox
Phone: 603-315-7520
Email: rebecca.cox@gza.com

Attn: Lucas Turcotte
Phone: 603-380-5017
Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- None

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 9.4

Observations/Notes: Standing water within and extending approx. 10" beyond culvert inlet into stone area, approx. max depth 3.5"

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: ---

Observations/Notes:

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.6

Observations/Notes: Standing water extending approx. 10" from culvert inlet into stone riprap area, standing water approx. 3" deep

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 6.8

Observations/Notes: Standing water extending approx. 16" beyond culvert outlet, approx. 8" deep

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 2 (Downstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Knight's Brook – 3 (Above Duct Bank in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 1 (Wetland NW-22)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Hannah – 2 (Wetland NW-24)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location: Flynn Pit – 1 (Wetland NW-4)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

Location:

Status of surface water at the time of inspection? Dry Standing Flowing

pH:

Observations/Notes:

OTHER COMMENTS AND OBSERVATIONS

- None