

# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust. **TYPE OF INSPECTION:** □ Daily □ Weekly Storm Event<sup>+</sup> □ Reduced Frequency<sup>++</sup> Other: Time: **0940** <sup>+</sup>Was this inspection triggered by a 0.25" storm event? □ Yes ⊠ No Date: 01/28/2021 If yes, how did you determine whether a 0.25" storm event has occurred? Other If other, please describe Weather Underground +Storm event info (approx): Light snow and wintery mix beginning late evening on 12/26 and continuing intermittently through 12/27 and into afternoon of 12/28 Amount of rainfall (inches): 0.12 ++Reason for Reduced Frequency (i.e., Monthly due to dry conditions): Inspector name(s) and title(s): Matt Deane, Technical Specialist Others present/affiliation(s):

Weather conditions (since last inspection): Intermittent sun and clouds, light snow and wintery mix beginning late evening on 12/26 and continuing intermittently through 12/27 and into afternoon of 12/28 Weather conditions (time of inspection): Light Snow, Low 30's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: 01/28/2021 Time: 0935 Notes:

#### **PROJECT TEAM**

PROJECT OWNER		ENVIRO	ENVIRONMENTAL CONSULTANT	
Eversource		GZA GeoEnvironmental, Inc.		
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier	
Phone:	508-954-2736	Phone:	603-380-5024	
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com	
•		•		
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox	
Phone:	603-714-3031	Phone:	603-315-7520	
Email:	kurt.nelson@eversource.com	Email:	rebecca.cox@gza.com	
Attn:	Tom Meister	Attn:	Lucas Turcotte	
Phone:	339-987-7901	Phone:	603-380-5017	
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com	
			-	
Attn:	Sam Eames			
Phone:	603-915-0073			
Email:	samual eames@eversource.com			
EVERSOURCE COMPLIANCE				
Attn:	Matt Cardin			
Phone:	603-988-6635			
Email:	matthew.cardin@eversource.com			
FIELD SERVICES SAFETY MANAGER				
Transmission ROW				
Attn:	Joshua Scott			
Phone:	603-848-7759			
Email:	Joshua.scott@eversource.com			

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No: 04.0190967.00

### CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

• None

PHOTOGRAPHS





29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



4 Brickyard Circle – 1 (Drainage Course)

29 Gundalow - 2 (Culvert)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle – 2 (Drainage Course)

Page 3 of 5

## PHOTOGRAPHS



4 Brickyard Circle – 3 (Drainage Course)

Page 4 of 5

DRAINAGE AREA MONITORING					
Location: 29 Gundalow – 1 (Drainage Area)   Status of surface water at the time of inspection? ⊠ Dry   Standing ☐ Flowing					
pH:					
Observations/Notes:					
Location: 29 Gundalow – 2 (Culvert)   Status of surface water at the time of inspection? □ Dry □ Standing ⊠ Flowing   pH: 12.4					
Observations/Notes: Water extending approx. 12" beyond culvert inlet into stone area, approx. max depth 4". Water frozen at surface.					
Location: 64 Gundalow – 1 (Drainage Course)					
Status of surface water at the time of inspection? Dry Standing Flowing					
Observations/Notes: Accessible water frozen through to substrate.					
Location: 64 Gundalow – 2 (Drainage Course) Status of surface water at the time of inspection?					
Status of surface water at the time of inspection? Dry Standing Flowing					
Observations/Notes: Flowing water extending approx. 3" beyond culvert inlet, approx. 1" deep.					
Location: 4 Brickyard Circle – 1 (Drainage Course)   Status of surface water at the time of inspection? Dry Standing Flowing   pH: 9.4					
Observations/Notes: Standing water extending approx.2' from outlet, max depth approx. 8". Water frozen at surface.					
Location: 4 Brickyard Circle – 2 (Drainage Course)   Status of surface water at the time of inspection? Dry   Standing Standing   pH: 7.7					
Observations/Notes: Flowing water adjacent to east wall of raceway, approx. 2" deep. Water frozen at surface.					
Location: 4 Brickyard Circle – 3 (Drainage Course)   Status of surface water at the time of inspection? Dry   Standing Standing   pH: 7.4					
Observations/Notes: Flowing water in center of raceway, approx. 2" deep. Water frozen at surface.					
Location: Knight's Brook – 1 (Upstream in Brook)   Status of surface water at the time of inspection?    Dry    Standing    Flowing					
pH: Not Monitored					
Observations/Notes:					

	_			
Location: Knight's Brook – 2 (Downstream in Brook)				
Status of surface water at the time of inspection?				
pH: Not Monitored				
Observations/Notes:				
Location: Knight's Brook – 3 (Above Duct Bank in Brook)				
Status of surface water at the time of inspection?				
pH: Not Monitored				
Observations/Notes:				
Location: Hannah – 1 (Wetland NW-22)				
Status of surface water at the time of inspection?				
pH: Not Monitored				
Observations/Notes:				
Location: Hannah – 2 (Wetland NW-24)				
Status of surface water at the time of inspection?				
pH: Not Monitored				
Observations/Notes:				
Location: Flynn Pit – 1 (Wetland NW-4)				
Status of surface water at the time of inspection?				
pH: Not Monitored				
Observations/Notes:				
Location:	_			
Status of surface water at the time of inspection?				
pH:				
Observations/Notes:				

#### OTHER COMMENTS AND OBSERVATIONS

• None.