

# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

TYPE OF INSPECTION:	□ Daily □ Weekly ⊠ Storm Event <sup>+</sup> □ Reduced Frequency <sup>++</sup>		
Date: 02/16/2021 Time: 132	20 <sup>+</sup> Was this inspection triggered by a 0.25" storm event? ⊠ Yes □ No		
If yes, how did you determine whether a 0.25" storm event has occurred? ☐ Rain Gauge ☐ Weather Station			
+Storm event info (approx): Wintery mix and variable rain beginning early morning on 2/16 and continuing through the early afternoon			
Amount of rainfall (inches): 0.38			
++Reason for Reduced Frequency (i.e., Monthly due to dry conditions):			
Inspector name(s) and title(s): Matt Deane, Technical Specialist			
Others present/affiliation(s):			

Weather conditions (since last inspection): Variable sun, clouds, and snow with temperatures consistently below freezing until 2/16 storm event

Weather conditions (time of inspection): Cloudy, Mid 30's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: 02/16/2021 Time: 1315 Notes:

#### **PROJECT TEAM**

PROJECT OWNER		ENVIRONMENTAL CONSULTANT	
Eversource		GZA GeoEnvironmental, Inc.	
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier
Phone:	508-954-2736	Phone:	603-380-5024
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox
Phone:	603-714-3031	Phone:	603-315-7520
Email:	kurt.nelson@eversource.com	Email:	rebecca.cox@gza.com
Attn:	Tom Meister	Attn:	Lucas Turcotte
Phone:	339-987-7901	Phone:	603-380-5017
Email:	thomas.meister@eversource.com	Email:	lucas.turcotte@gza.com
Attn:	Sam Eames		
Phone:	603-915-0073		
Email:	samual eames@eversource.com		
EVERSOURCE COMPLIANCE			
Attn:	Matt Cardin		
Phone:	603-988-6635		
Email:	matthew.cardin@eversource.com		
FIELD SERVICES SAFETY MANAGER			
	ssion ROW		
Attn:	Joshua Scott		
Phone:	603-848-7759		
Email:	Joshua.scott@eversource.com		

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No: 04.0190967.00

## CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

None

PHOTOGRAPHS

29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



4 Brickyard Circle – 1 (Drainage Course)



29 Gundalow - 2 (Culvert)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle – 2 (Drainage Course)

Page 3 of 5

## PHOTOGRAPHS



4 Brickyard Circle – 3 (Drainage Course)

DRAINAGE AREA MONITORING				
Location: 29 Gundalow – 1 (Drainage Area)         Status of surface water at the time of inspection?       Image: Dry ima				
Observations/Notes: No water observed under snow cover.				
Location: 29 Gundalow – 2 (Culvert)         Status of surface water at the time of inspection?       Dry         Standing       Flowing         pH: Frozen				
Observations/Notes: Layer of slush/snow melt on top of solid ice layer.				
Location:       64 Gundalow – 1 (Drainage Course)         Status of surface water at the time of inspection? <ul> <li>Dry</li> <li>Standing</li> <li>Flowing</li> </ul> pH:       11.0				
Observations/Notes: Flowing water under layer of snow.				
Location: 64 Gundalow – 2 (Drainage Course)         Status of surface water at the time of inspection?       □ Dry       □ Standing       ☑ Flowing         pH: 10.5       Observations/Notes: Flowing water under layer of snow.				
Location: 4 Brickyard Circle – 1 (Drainage Course)         Status of surface water at the time of inspection?       □ Dry       □ Standing       ☑ Flowing         pH: 9.6       Observations/Notes: Some solid ice and flowing water at culvert outlet.				
Location: 4 Brickyard Circle – 2 (Drainage Course)         Status of surface water at the time of inspection?       □ Dry       □ Standing       ☑ Flowing         pH: 7.9				
Observations/Notes: Some liquid flowing water, predominantly heavy slush in raceway.				
Location: 4 Brickyard Circle – 3 (Drainage Course)         Status of surface water at the time of inspection?       □ Dry       □ Standing       ☑ Flowing         pH: 7.6				
Observations/Notes: Some liquid flowing water, predominantly heavy slush in raceway.				
Location:       Knight's Brook – 1 (Upstream in Brook)         Status of surface water at the time of inspection?       Dry         Standing       Flowing         pH:       Not Monitored         Observations/Notes:       Dry				

Location: Knight's Brook – 2 (Downstream in Brook)
Status of surface water at the time of inspection?
pH: Not Monitored
Observations/Notes:
Location: Knight's Brook – 3 (Above Duct Bank in Brook)
Status of surface water at the time of inspection?
pH: Not Monitored
Observations/Notes:
Location: Hannah – 1 (Wetland NW-22)
Status of surface water at the time of inspection?
pH: Not Monitored
Observations/Notes:
Location: Hannah – 2 (Wetland NW-24)
Status of surface water at the time of inspection?
pH: Not Monitored
Observations/Notes:
Location: Flynn Pit – 1 (Wetland NW-4)
Status of surface water at the time of inspection?
pH: Not Monitored
Observations/Notes:
Location:
Status of surface water at the time of inspection?
pH:
Observations/Notes:

### OTHER COMMENTS AND OBSERVATIONS

• None.