



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION: Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **02/23/2021** Time: **0930** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe: Weather Underground

+Storm event info (approx): Light snow beginning early afternoon then changing to light rain and continuing through the evening

Amount of rainfall (inches): 0.15

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds until afternoon of 2/22 with light snow changing to light rain

Weather conditions (time of inspection): Partly Cloudy, High 20's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **02/23/2021** Time: **0925**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: kurt.nelson@eversource.com

Attn: Tom Meister

Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Sam Eames

Phone: 603-915-0073

Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox

Phone: 603-315-7520

Email: rebecca.cox@gza.com

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: lucas.turcotte@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- None

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)



4 Brickyard Circle - 2 (Drainage Course)

PHOTOGRAPHS



4 Brickyard Circle – 3 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: --

Observations/Notes: No water observed under snow cover.

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 12.3

Observations/Notes: Approx. 7" of standing water within culvert inlet.

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 12.1

Observations/Notes: Flowing water under layer of snow and ice.

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 10.5

Observations/Notes: Flowing water under layer of snow.

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 9.5

Observations/Notes: Some solid ice and flowing water at culvert outlet.

Location: 4 Brickyard Circle – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 8.0

Observations/Notes: Water flowing under snow and ice layer.

Location: 4 Brickyard Circle – 3 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.6

Observations/Notes: Water flowing under snow and ice layer.

Location: Knight's Brook – 1 (Upstream in Brook)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: **Not Monitored**

Observations/Notes:

<p>Location: Knight's Brook – 2 (Downstream in Brook) Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Not Monitored Observations/Notes:</p>
<p>Location: Knight's Brook – 3 (Above Duct Bank in Brook) Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Not Monitored Observations/Notes:</p>
<p>Location: Hannah – 1 (Wetland NW-22) Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Not Monitored Observations/Notes:</p>
<p>Location: Hannah – 2 (Wetland NW-24) Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Not Monitored Observations/Notes:</p>
<p>Location: Flynn Pit – 1 (Wetland NW-4) Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Not Monitored Observations/Notes:</p>
<p>Location: Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Observations/Notes:</p>

<p>OTHER COMMENTS AND OBSERVATIONS</p> <ul style="list-style-type: none">• None.
