

DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT Known for excellence. Built on trust.

TYPE OF INSPECTION:	□ Daily □ Weekly 🛛 Storm Event ⁺ □ Reduced Frequency ⁺⁺			
	Other:			
Date: 03/19/2021 Time: 09	955 ⁺ Was this inspection triggered by a 0.25" storm event? \boxtimes Yes \square No			
If yes, how did you determine whether a 0.25" storm event has occurred? □ Rain Gauge □ Weather Station ☑ Other If other, please describe: Weather Underground				
+Storm event info (approx): Light rain on 3/18 beginning mid-afternoon and ending late evening				
Amount of rainfall (inches): 0.33				
++Reason for Reduced Frequency (<i>i.e., Monthly due to dry conditions</i>):				

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds, no measurable precipitation

Weather conditions (time of inspection): Sunny, Windy, High 20's

pH Meter Information (make/model): Hanna HI98107

Calibration Method: 2 Point Date: 03/19/2021 Time: 0915 Notes:

PROJECT TEAM

PROJECT	Γ OWNER	ENVIRON	MENTAL CONSULTANT	
Eversource		-	GZA GeoEnvironmental, Inc.	
Attn:	Dena Champy-Project Manager	Attn:	Deborah Zarta Gier	
Phone:	508-954-2736	Phone:	603-380-5024	
Email:	dena.champy@eversource.com	Email:	Deborah.zartagier@gza.com	
Eman.	<u>dona.onampy Govorodaroo.oom</u>	Email	Deboranizanagior egza.com	
Attn:	Kurt Nelson-Permitting Specialist	Attn:	Rebecca Cox	
Phone:	603-714-3031	Phone:	603-315-7520	
Email:	kurt.nelson@eversource.com	Email:	rebecca.cox@gza.com	
Email		Email		
Attn:	Tom Meister			
Phone:	339-987-7901			
Email:	thomas.meister@eversource.com			
Attn:	Sam Eames			
Phone:	603-915-0073			
Email:	samual eames@eversource.com			
EVERSO	URCE COMPLIANCE			
Attn:	Matt Cardin			
Phone:	603-988-6635			
Email:	matthew.cardin@eversource.com			
FIFLD SE	RVICES SAFETY MANAGER			
	sion ROW			
Attn:	Joshua Scott			
Phone:	603-848-7759			
Email:	Joshua.scott@eversource.com			
<u> </u>				

Eversource Transmission Line:

F107 - Seacoast Reliability Project

Location:

Durham, New Hampshire

GZA Project No: 04.0190967.00

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

Active construction/earthwork occurring in adjacent parking lot.

PHOTOGRAPHS

•



UNH Wetland - 1 (Stormwater Area)



UNH Wetland - 3 (Cattail Wetland)



UNH Wetland - 5 (Cattail Wetland)



UNH Wetland – 2 (Stormwater Area)



UNH Wetland - 4 (Cattail Wetland)



UNH Wetland - 6 (Cattail Wetland)

DRAINAGE AREA MONITORING						
Location: UNH Wetland – 1 (Stormwater Area) Status of surface water at the time of inspection? Image: Dry i						
Location: UNH Wetland – 2 (Stormwater Area) Status of surface water at the time of inspection? □ Dry ⊠ Standing □ Flowing pH: 7.5						
Observations/Notes: Approx. 2" standing water with some areas of ice.						
Location: UNH Wetland – 3 (Cattail Wetland) Status of surface water at the time of inspection? Dry Standing Flowing pH: 7.7						
Observations/Notes: Intermittent ice with standing water approx. 4" deep.						
Location: UNH Wetland – 4 (Cattail Wetland) Status of surface water at the time of inspection? □ Dry ⊠ Standing □ Flowing pH: 6.9						
Observations/Notes: Intermittent ice with standing water approx. 6" deep.						
Location: UNH Wetland – 5 (Cattail Wetland) Status of surface water at the time of inspection? □ Dry ⊠ Standing □ Flowing pH: 6.9						
Observations/Notes: Intermittent ice with standing water approx. 6" deep.						
Location: UNH Wetland – 6 (Cattail Wetland) Status of surface water at the time of inspection? Image: Dry i						
Observations/Notes: Soil saturated with some minimal standing water, not enough to obtain pH measurement.						
Location: College Brook – 1 (Upstream in Brook) Status of surface water at the time of inspection? Dry Standing Flowing pH: Not Monitored						
Observations/Notes:						
Location: College Brook – 2 (Downstream in Brook) Status of surface water at the time of inspection? Dry Standing Flowing						
pH: Not Monitored						
Observations/Notes:						

Eversource Energy Seacoast Reliability Project Project #04.0190967.00

Location: CB – 1 (Catch Basin) Status of surface water at the time of inspection? pH: Not Monitored Observations/Notes:	🗌 Dry	Standing	Flowing
Observations/Notes.			
Location: CB – 2 (Catch Basin)) Status of surface water at the time of inspection? pH: Not Monitored Observations/Notes:	Dry	Standing	Flowing
Location: RG – 1 (Rain Garden) Status of surface water at the time of inspection? pH: Not Monitored Observations/Notes:	Dry	Standing	Flowing
Location: A Lot – 1 (Drainage Swale)			
Status of surface water at the time of inspection? pH: Not Monitored Observations/Notes:	Dry	Standing	Flowing
Location: Reservoir Brook – 1 (Brook)			
Status of surface water at the time of inspection? pH: Not Monitored Observations/Notes:	🗌 Dry	Standing	Flowing
Location:			
Status of surface water at the time of inspection? pH: Observations/Notes:	Dry	Standing	Flowing

OTHER COMMENTS AND OBSERVATIONS

• Thin layer of surface ice at monitoring locations UNH Wetland – 2 through UNH Wetland – 5.