

DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

TYPE OF INSPECTION: ☐ Daily ☐ Weekly ☐ Storm Event ☐ Reduced Frequency ☐ Other:
Date: 03/19/2021 Time: 0920 *Was this inspection triggered by a 0.25" storm event? ☑ Yes ☐ No If yes, how did you determine whether a 0.25" storm event has occurred? ☐ Rain Gauge ☐ Weather Station ☑ Other If other, please describe: Weather Underground +Storm event info (approx): Light rain on 3/18 beginning mid-afternoon and ending late evening Amount of rainfall (inches): 0.33 ++Reason for Reduced Frequency (i.e., Monthly due to dry conditions):
Inspector name(s) and title(s): Matt Deane, Technical Specialist
Others present/affiliation(s):
Weather conditions (since last inspection): Variable sun and clouds, no measurable precipitation
Weather conditions (time of inspection): Sunny, Windy, High 20's
pH Meter Information (make/model): Hanna HI98107
Calibration Method: 2 Point Date: 03/19/2021 Time: 0915
Notes:

PROJECT TEAM

PROJECT OWNER

Eversource
Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: <u>kurt.nelson@eversource.com</u>

Attn: Tom Meister Phone: 339-987-7901

Email: thomas.meister@eversource.com

Attn: Sam Eames Phone: 603-915-0073

Email: <u>samual eames@eversource.com</u>

EVERSOURCE COMPLIANCE

Attn: Matt Cardin Phone: 603-988-6635

Email: <u>matthew.cardin@eversource.com</u>

FIELD SERVICES SAFETY MANAGER

Transmission ROWAttn: Joshua Scott
Phone: 603-848-7759

Email: Joshua.scott@eversource.com

F107 - Seacoast

Eversource Transmission

Reliability Project

Location:

ENVIRONMENTAL CONSULTANT

Rebecca Cox

603-315-7520

Deborah Zarta Gier 603-380-5024

rebecca.cox@gza.com

Deborah.zartagier@gza.com

GZA GeoEnvironmental, Inc.

Attn:

Phone:

Email:

Attn:

Phone:

Email:

Line:

Newington, New Hampshire

GZA Project No:

04.0190967.00

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

None

PHOTOGRAPHS



29 Gundalow -1 (Drainage Area)



64 Gundalow - 1 (Drainage Course)



4 Brickyard Circle – 1 (Drainage Course)



29 Gundalow - 2 (Culvert)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 2 (Drainage Course)

PHOTOGRAPHS



4 Brickyard Circle – 3 (Drainage Course)

DRAINAGE AREA MONITORING
Location: 29 Gundalow – 1 (Drainage Area) Status of surface water at the time of inspection?
Observations/Notes: Soil saturated and partially frozen
Location: 29 Gundalow – 2 (Culvert) Status of surface water at the time of inspection? ☐ Dry ☐ Standing ☑ Flowing pH: 11.9
Observations/Notes: Approx. 5" of flowing water at culvert inlet. Film of precipitate observed on stone and leaf litter under water surface.
Location: 64 Gundalow – 1 (Drainage Course) Status of surface water at the time of inspection? □ Dry □ Standing □ Flowing pH: 11.7
Observations/Notes: Accessible flowing water extending approx. 2' beyond culvert outlet, leaf litter in drainage course.
Location: 64 Gundalow – 2 (Drainage Course) Status of surface water at the time of inspection? □ Dry □ Standing ☑ Flowing pH: 10.1 Observations/Notes: Area of intermittent water extending approx. 18" from culvert inlets.
Location: 4 Brickyard Circle − 1 (Drainage Course) Status of surface water at the time of inspection? □ Dry □ Standing ☑ Flowing pH: 9.2
Observations/Notes: Flowing water in drainage course extending approx. 2' from culvert outlets, max depth approx. 8".
Location: 4 Brickyard Circle – 2 (Drainage Course) Status of surface water at the time of inspection? ☐ Dry ☐ Standing ☑ Flowing pH: 7.6
Observations/Notes: Water flowing approx. 2" deep, some ice still in raceway.
Location: 4 Brickyard Circle – 3 (Drainage Course) Status of surface water at the time of inspection? □ Dry □ Standing ☑ Flowing pH: 7.4
Observations/Notes: Water flowing approx. 3" deep, thin layer of ice on surface.
Location: Knight's Brook – 1 (Upstream in Brook) Status of surface water at the time of inspection?
Observations/Notes:

DRAINAGE MONITORING REPORT

Page 5 of 5

Location: Knight's Brook – 2 (Downstream in Brook) Status of surface water at the time of inspection? Dry Standing Flowing
pH: Not Monitored
Observations/Notes:
Location: Knight's Brook – 3 (Above Duct Bank in Brook)
Status of surface water at the time of inspection? Dry Standing Flowing
pH: Not Monitored
Observations/Notes:
Location: Hannah – 1 (Wetland NW-22)
Status of surface water at the time of inspection? Dry Standing Flowing
pH: Not Monitored
Observations/Notes:
Location: Hannah – 2 (Wetland NW-24)
Status of surface water at the time of inspection? Dry Standing Flowing
pH: Not Monitored
Observations/Notes:
Location: Flynn Pit – 1 (Wetland NW-4)
Status of surface water at the time of inspection? Dry Standing Flowing
pH: Not Monitored
Observations/Notes:
Location:
Status of surface water at the time of inspection? Dry Standing Flowing
pH:
Observations/Notes:
OTHER COMMENTS AND OBSERVATIONS
None.