



DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission
Line:

F107 - Seacoast Reliability Project

Location:

Newington, New Hampshire

GZA Project No:

04.0190967.00

TYPE OF INSPECTION:

- Daily Weekly Storm Event⁺ Reduced Frequency⁺⁺
 Other:

Date: **04/08/2021** Time: **0925** ⁺Was this inspection triggered by a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
 Other If other, please describe:

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Primarily sunny, no measurable precipitation

Weather conditions (time of inspection): Sunny, Mid 50's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **04/08/2021** Time: **0920**

Notes:

PROJECT TEAM

PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager
Phone: 508-954-2736
Email: dena.champy@eversource.com

Attn: Kurt Nelson-Permitting Specialist
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Tom Meister
Phone: 339-987-7901
Email: thomas.meister@eversource.com

Attn: Sam Eames
Phone: 603-915-0073
Email: samual.eames@eversource.com

EVERSOURCE COMPLIANCE

Attn: Matt Cardin
Phone: 603-988-6635
Email: matthew.cardin@eversource.com

FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott
Phone: 603-848-7759
Email: joshua.scott@eversource.com

ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier
Phone: 603-380-5024
Email: Deborah.zartagier@gza.com

Attn: Rebecca Cox
Phone: 603-315-7520
Email: rebecca.cox@gza.com

CURRENT/RECENT SITE WORK ACTIVITIES / NOTES

- Peat moss socks installed in drainage areas on 29 Gundalow Landing (1), 64 Gundalow Landing (3), and 4 Brickyard Circle (1) on the morning of 04/02/2021.

PHOTOGRAPHS



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)



4 Brickyard Circle - 2 (Drainage Course)

PHOTOGRAPHS



4 Brickyard Circle – 3 (Drainage Course)

DRAINAGE AREA MONITORING

Location: 29 Gundalow – 1 (Drainage Area)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: --

Observations/Notes: Soil saturated, not enough standing water to obtain measurement.

Location: 29 Gundalow – 2 (Culvert)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 12.6

Observations/Notes: Approx. 6" of flowing water at culvert inlet.

Location: 64 Gundalow – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 12.1

Observations/Notes: Accessible flowing water extending approx. 6" beyond culvert outlet.

Location: 64 Gundalow – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 8.1

Observations/Notes: Area of intermittent water extending approx. 10" from culvert inlets.

Location: 4 Brickyard Circle – 1 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.3

Observations/Notes: Flowing water in drainage course extending approx. 18" from culvert outlets, max depth approx. 8".

Location: 4 Brickyard Circle – 2 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.2

Observations/Notes: Water flowing approx. 2" deep.

Location: 4 Brickyard Circle – 3 (Drainage Course)

Status of surface water at the time of inspection? Dry Standing Flowing

pH: 7.2

Observations/Notes: Water flowing approx. 3" deep.

OTHER COMMENTS AND OBSERVATIONS

- None.