



CONSTRUCTION MONITORING REPORT



Eversource Transmission Lines:
F107

**Madbury, Durham,
Newington, Portsmouth, NH**

Alteration of Terrain Permit:
SEC Docket No. 2015-004

Environmental Permit:
SEC Docket No. 2015-004

USEPA NOI Tracking No:
**NHR1000QN
NHR1000QT
NHR1000QO
NHR1000S6**

NAI Project No:
23840.39

TYPE OF INSPECTION: Weekly Storm Event Incident Corrective Action

Date of inspection: **04/26/21** Start Time: **11:45am** Previous inspection: **04/20/21**

Does this report include a 0.25" storm event? Yes No

If yes, how did you determine whether a 0.25" storm event has occurred? Rain Gauge Weather Station
Storm event information is from Portsmouth International Airport at Pease.

+Storm event information (approx.): Start date: Amount (inches):

NOTE:

Inspector name(s), title(s) and qualifications: **Elizabeth Olliver, Normandeau Environmental Inspector and Marc Jacobs, CPESC, NHCWS**

Others present/qualifications(s):

Weather conditions (since last inspection): **Cloudy Wednesday with light rain in the evening. Total precipitation of 0.19 inches. Partly cloudy Thursday with trace precipitation Thursday evening. Mostly sunny Friday through Saturday changing to cloudy Sunday with light rain during the day. Total precipitation of 0.04 inches. Temperatures in the low 30s to high 60s.**

Weather conditions (time of inspection & future outlook): **Mostly sunny Monday and Tuesday changing to cloudy Wednesday with showers predicted to begin during the day and continue through Friday evening. Partly sunny Saturday changing to mostly sunny Sunday and Monday. Temperatures in the low 40s to high 60s.**

CONSTRUCTION SITE SEQUENCING AND DISTURBANCE

Disturbed area and ongoing work (acreage & description): < 1 acre

Proceeding per approved plan? Yes No, if not, note area and explain:

Operating within phasing limitations? Yes No, if not, note area and explain:

General Comments:

- In addition to the usual sensitive areas, a spot check of Structures 30-34 was conducted.

Work completed this week:

- *Portsmouth*
 - *None - construction and restoration complete. Post-construction inspections are continuing.*
- *Madbury*
 - *None – construction and restoration complete. Post-construction inspections are continuing.*
- *Newington*
 - *None – construction and restoration complete. Post-construction inspections are continuing.*
- *Durham*
 - *None – construction and restoration complete. Post-construction inspections are continuing.*

Erosion and sediment control items and observations:

- **BMPs**
 - All remaining BMPs should be left in place until the sites are determined to be stabilized by the environmental monitor.

Corrective Action:

- None

PHOTOGRAPHS



Fig 1: Upper portion of slope leading down to cable house and salt marsh restoration at the west side of the bay. Viewing east. (04-26-21)



Fig 2: Slope between the cable house and salt marsh restoration at the west side of the bay. Viewing south. (04-26-21)

PHOTOGRAPHS



Fig 3: Slope above the cable house at the west side of the bay. Viewing northwest. (04-26-21)



Fig 4: Toe of the slope and salt marsh restoration at the west side of the bay. Viewing south. (04-26-21)

PHOTOGRAPHS



Fig 5: Str. 89 work area. Viewing southeast. (04-26-21)



Fig 6: Str. 90 work area. Viewing northeast. (04-26-21)

PHOTOGRAPHS



Fig 7: Stream DS46 between Strs. 51 and 52. Viewing northeast. (04-26-21)



Fig 8: Lower portion of slope between Strs. 28 and 29. Viewing northeast. (04-26-21)

PHOTOGRAPHS



Fig 9: Slope above the manhole at Gundalow Landing/east side of the bay. Viewing east. (04-26-21)



Fig 10: Slope below the manhole at Gundalow Landing/east side of the bay. Viewing east. (04-26-21)

PHOTOGRAPHS



Fig 11: Toe of the slope at Gundalow Landing/east side of the bay. Viewing south. (04-26-21)



Fig 12: Salt marsh restoration at Gundalow Landing/east side of the bay. Viewing south. (04-26-21)



Fig 13: Str. 33 work area. Viewing southwest. (04-26-21)



Fig 14: Str. 34 work area. Viewing west. (04-26-21)

PROJECT TEAM

Eversource

Attn: Dena Champy-Eversource Project Manager
Phone: 603-634-2891
Email: dena.champy@eversource.com

Attn: Joseph Sperry-Eversource Senior Engineer
Phone: 603-634-2562
Email: joseph.sperry@eversource.com

Attn: Kurt Nelson-Eversource Permitting
Phone: 603-714-3031
Email: kurt.nelson@eversource.com

Attn: Sarah Hoodlet-Municipal Outreach
Phone: 603-995-1593
Email: sarah.hoodlet@eversource.com

Attn: Sam Eames-Construction Rep
Phone: 603-915-0073
Email: sam.eames@eversource.com

Attn: Thomas Meister-Construction Rep
Phone: 339-987-7901
Email: Thomas.meister@eversource.com

Attn: Joshua Scott-ROW Safety Mgr
Phone: 603-848-7759
Email: Joshua.scott@eversource.com

Contractors

JCR Utility Construction Co., Inc.
Attn: Matt Moreau-Project Manager
Phone: 603-895-4062
Email: matt.moreau@crutility.com

McCourt Construction
Attn: Michael Worhunsky-Project Manager
Phone: 617-293-3864
Email: mworhunsky@mccourtconstruction.com

Attn: Scott Gorman-Safety Director
Phone: 617-828-8822
Email: sgorman@mccourtconstruction.com

Attn: Dan Cedrone-Superintendent
Phone: 617-908-2660
Email: dcedrone@mccourtconstruction.com

Supreme Industries
Attn: Jamieson Boucher
Phone: 860-485-4101
Email: dcedrone@mccourtconstruction.com

GZA
Attn: Logan Young
Phone: 603-213-1810
Email: logan.young@gza.com

Environmental Consultant

Normandeau Associates, Inc.
Attn: Elizabeth Olliver-Environmental Monitor
Phone: 603-714-1231
Email: eolliver@normandeau.com

Attn: Marc Jacobs-CPESC, NHCWS
Phone: 603-534-7645
Email: jacobs2wetsoil2004@yahoo.com

Attn: Sarah Allen-Principal Wetland Scientist
Phone: 603-714-3085
Email: sallen@normandeau.com