



# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission  
Line:

## F107 - Seacoast Reliability Project

Location:

### Newington, New Hampshire

GZA Project No:

04.0190967.00

**TYPE OF INSPECTION:**  Daily  Weekly  Storm Event<sup>+</sup>  Reduced Frequency<sup>++</sup>  
 Other:

Date: **01/03/2021** Time: **1120** <sup>+</sup>Was this inspection triggered by a 0.25" storm event?  Yes  No

If yes, how did you determine whether a 0.25" storm event has occurred?  Rain Gauge  Weather Station  
 Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency  
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds, no measurable precipitation

Weather conditions (time of inspection): Mostly Cloudy, Low 30's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **01/03/2021** Time: **1115**

Notes:

## PROJECT TEAM

### PROJECT OWNER

#### Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: [dena.champy@eversource.com](mailto:dena.champy@eversource.com)

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: [kurt.nelson@eversource.com](mailto:kurt.nelson@eversource.com)

Attn: Tom Meister

Phone: 339-987-7901

Email: [thomas.meister@eversource.com](mailto:thomas.meister@eversource.com)

Attn: Sam Eames

Phone: 603-915-0073

Email: [samual.eames@eversource.com](mailto:samual.eames@eversource.com)

### EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: [matthew.cardin@eversource.com](mailto:matthew.cardin@eversource.com)

### FIELD SERVICES SAFETY MANAGER

#### Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: [joshua.scott@eversource.com](mailto:joshua.scott@eversource.com)

### ENVIRONMENTAL CONSULTANT

#### GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: [Deborah.zartagier@gza.com](mailto:Deborah.zartagier@gza.com)

Attn: Rebecca Cox

Phone: 603-315-7520

Email: [rebecca.cox@gza.com](mailto:rebecca.cox@gza.com)

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: [lucas.turcotte@gza.com](mailto:lucas.turcotte@gza.com)

**CURRENT/RECENT SITE WORK ACTIVITIES / NOTES**

- None

**PHOTOGRAPHS**



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)



4 Brickyard Circle - 2 (Drainage Course)

**PHOTOGRAPHS**



4 Brickyard Circle – 3 (Drainage Course)

**DRAINAGE AREA MONITORING**

**Location: 29 Gundalow – 1 (Drainage Area)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: --

Observations/Notes: Ground surface frozen

**Location: 29 Gundalow – 2 (Culvert)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 12.6

Observations/Notes: Water extending approx. 12" beyond culvert inlet into stone area, approx. max depth 4". Flow visible through culvert.

**Location: 64 Gundalow – 1 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 12.3

Observations/Notes: Flowing water extending approx. 18" beyond culvert outlet, approx. 1" deep.

**Location: 64 Gundalow – 2 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 10.3

Observations/Notes: Flowing water extending approx. 6" beyond culvert inlet, approx. 1" deep.

**Location: 4 Brickyard Circle – 1 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 9.7

Observations/Notes: Standing water extending approx. 18" from outlet, max depth approx. 8".

**Location: 4 Brickyard Circle – 2 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 7.9

Observations/Notes: Flowing water adjacent to east wall of raceway, approx. 1" deep.

**Location: 4 Brickyard Circle – 3 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 7.6

Observations/Notes: Flowing water in center of raceway, approx. 2" deep.

**Location: Knight's Brook – 1 (Upstream in Brook)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location: Knight's Brook – 2 (Downstream in Brook)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location: Knight's Brook – 3 (Above Duct Bank in Brook)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location: Hannah – 1 (Wetland NW-22)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location: Hannah – 2 (Wetland NW-24)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location: Flynn Pit – 1 (Wetland NW-4)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

**Location:**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH:

Observations/Notes:

**OTHER COMMENTS AND OBSERVATIONS**

- None.



# DRAINAGE MONITORING REPORT

GEOTECHNICAL | ENVIRONMENTAL | ECOLOGICAL | WATER | CONSTRUCTION MANAGEMENT

Known for excellence. Built on trust.

Eversource Transmission  
Line:

## F107 - Seacoast Reliability Project

Location:

### Newington, New Hampshire

GZA Project No:

04.0190967.00

#### TYPE OF INSPECTION:

- Daily  Weekly  Storm Event<sup>+</sup>  Reduced Frequency<sup>++</sup>  
 Other:

Date: **01/08/2021** Time: **0820** <sup>+</sup>Was this inspection triggered by a 0.25" storm event?  Yes  No

If yes, how did you determine whether a 0.25" storm event has occurred?  Rain Gauge  Weather Station  
 Other If other, please describe

+Storm event info (approx):

Amount of rainfall (inches):

++Reason for Reduced Frequency  
(i.e., Monthly due to dry conditions):

Inspector name(s) and title(s): Matt Deane, Technical Specialist

Others present/affiliation(s):

Weather conditions (since last inspection): Variable sun and clouds with some snow showers, no measurable precipitation

Weather conditions (time of inspection): Sunny, Mid 20's

pH Meter Information (make/model): **Hanna HI98107**

Calibration Method: 2 Point

Date: **01/08/2021** Time: **0815**

Notes:

## PROJECT TEAM

### PROJECT OWNER

Eversource

Attn: Dena Champy-Project Manager

Phone: 508-954-2736

Email: [dena.champy@eversource.com](mailto:dena.champy@eversource.com)

Attn: Kurt Nelson-Permitting Specialist

Phone: 603-714-3031

Email: [kurt.nelson@eversource.com](mailto:kurt.nelson@eversource.com)

Attn: Tom Meister

Phone: 339-987-7901

Email: [thomas.meister@eversource.com](mailto:thomas.meister@eversource.com)

Attn: Sam Eames

Phone: 603-915-0073

Email: [samual.eames@eversource.com](mailto:samual.eames@eversource.com)

### EVERSOURCE COMPLIANCE

Attn: Matt Cardin

Phone: 603-988-6635

Email: [matthew.cardin@eversource.com](mailto:matthew.cardin@eversource.com)

### FIELD SERVICES SAFETY MANAGER

Transmission ROW

Attn: Joshua Scott

Phone: 603-848-7759

Email: [Joshua.scott@eversource.com](mailto:Joshua.scott@eversource.com)

### ENVIRONMENTAL CONSULTANT

GZA GeoEnvironmental, Inc.

Attn: Deborah Zarta Gier

Phone: 603-380-5024

Email: [Deborah.zartagier@gza.com](mailto:Deborah.zartagier@gza.com)

Attn: Rebecca Cox

Phone: 603-315-7520

Email: [rebecca.cox@gza.com](mailto:rebecca.cox@gza.com)

Attn: Lucas Turcotte

Phone: 603-380-5017

Email: [lucas.turcotte@gza.com](mailto:lucas.turcotte@gza.com)

**CURRENT/RECENT SITE WORK ACTIVITIES / NOTES**

- None

**PHOTOGRAPHS**



29 Gundalow - 1 (Drainage Area)



29 Gundalow - 2 (Culvert)



64 Gundalow - 1 (Drainage Course)



64 Gundalow - 2 (Drainage Course)



4 Brickyard Circle - 1 (Drainage Course)



4 Brickyard Circle - 2 (Drainage Course)

**PHOTOGRAPHS**



4 Brickyard Circle – 3 (Drainage Course)



**DRAINAGE AREA MONITORING**

**Location: 29 Gundalow – 1 (Drainage Area)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: --

Observations/Notes: Ground surface frozen

**Location: 29 Gundalow – 2 (Culvert)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 12.7

Observations/Notes: Water extending approx. 12" beyond culvert inlet into stone area, approx. max depth 4". Flow visible through culvert.

**Location: 64 Gundalow – 1 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 12.3

Observations/Notes: Flowing water extending approx. 18" beyond culvert outlet, approx. 1" deep.

**Location: 64 Gundalow – 2 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 10.5

Observations/Notes: Flowing water extending approx. 6" beyond culvert inlet, approx. 1" deep.

**Location: 4 Brickyard Circle – 1 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 9.8

Observations/Notes: Standing water extending approx. 18" from outlet, max depth approx. 8".

**Location: 4 Brickyard Circle – 2 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 7.8

Observations/Notes: Flowing water adjacent to east wall of raceway, approx. 1" deep.

**Location: 4 Brickyard Circle – 3 (Drainage Course)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: 7.5

Observations/Notes: Flowing water in center of raceway, approx. 2" deep.

**Location: Knight's Brook – 1 (Upstream in Brook)**

Status of surface water at the time of inspection?  Dry  Standing  Flowing

pH: **Not Monitored**

Observations/Notes:

<p><b>Location: Knight's Brook – 2 (Downstream in Brook)</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: <b>Not Monitored</b> Observations/Notes:</p>
<p><b>Location: Knight's Brook – 3 (Above Duct Bank in Brook)</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: <b>Not Monitored</b> Observations/Notes:</p>
<p><b>Location: Hannah – 1 (Wetland NW-22)</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: <b>Not Monitored</b> Observations/Notes:</p>
<p><b>Location: Hannah – 2 (Wetland NW-24)</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: <b>Not Monitored</b> Observations/Notes:</p>
<p><b>Location: Flynn Pit – 1 (Wetland NW-4)</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: <b>Not Monitored</b> Observations/Notes:</p>
<p><b>Location:</b> Status of surface water at the time of inspection? <input type="checkbox"/> Dry <input type="checkbox"/> Standing <input type="checkbox"/> Flowing pH: Observations/Notes:</p>

<p><b>OTHER COMMENTS AND OBSERVATIONS</b></p> <ul style="list-style-type: none"><li>• None.</li></ul>
---