

**STATE OF NEW HAMPSHIRE
SITE EVALUATION COMMITTEE**

21 SOUTH FRUIT STREET, SUITE 10
CONCORD, NEW HAMPSHIRE 03301

DANIEL C. GOLDNER
CHAIR



ANDREW E. BIEMER
ADMINISTRATOR

Commissioner Chicoine:

The Site Evaluation Committee (SEC) recently concluded a subcommittee investigation into the Antrim Wind Energy Facility LLC. The investigation found insufficient evidence to support a certificate violation and the SEC voted unanimously to take no enforcement action. [Docket 2021-02 is available here for your reference.](#)

While there was insufficient evidence to support a certificate violation, The SEC instructed me to notify you about monitoring issues regarding the Aircraft Detection Lighting System (ADLS). ALDS was a new technology at the time of its implementation at the Antrim Wind Energy Facility.

The Docket 2021-02 subcommittee investigation identified extended periods of time when the ADLS system was offline for repairs. The SEC therefore recommends that The Department of Energy (DOE) coordinate with the facility to evaluate a monitoring protocol.

Thank you and please contact me directly with any questions.

Andrew E. Biemer

Andrew Biemer

Administrator

Site Evaluation Committee