

EVERSOURCE ENERGY
SEACOAST RELIABILITY PROJECT
TABLE 1
pH Monitoring
Newington and Durham, New Hampshire

	WEEK 1							WEEK 2					WEEK 3					WEEK 4					WEEK 5		WEEK 6		WEEK 7	WEEK 8		
	June 5, 2020	June 7, 2020	June 8, 2020	June 9, 2020	June 10, 2020	June 11, 2020	June 12, 2020	June 15, 2020	June 16, 2020	June 17, 2020	June 18, 2020	June 19, 2020	June 22, 2020	June 23, 2020	June 24, 2020	June 25, 2020	June 26, 2020	June 29, 2020	June 30, 2020	July 1, 2020	July 2, 2020	July 3, 2020	July 6, 2020	July 9, 2020	July 14, 2020	July 17, 2020	July 23, 2020	July 29, 2020	July 30, 2020	July 31, 2020
NEWINGTON																														
29 Gundalow - 1 (Drainage Area)	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	10.0	9.6	9.5	9.3	8.6	8.5	NM	NM	NM	--	--	--	
29 Gundalow - 2 (Culvert)	9.2	8.8	6.8	8.0	8.3	7.4	7.0	8.2	8.3	7.8	7.3	7.9	7.9	7.9	7.6	8.0	7.9	8.0	9.3	9.5	9.2	9.2	8.6	8.5	10.1	9.5	8.4	--	--	--
64 Gundalow - 1 (Drainage Course)	7.5	7.7	7.4	7.5	7.7	7.3	7.0	--	--	--	--	--	7.7	--	--	--	--	8.6	8.7	8.6	8	7.7	7.6	NM	--	--	--	--	--	
64 Gundalow - 2 (Drainage Course)	6.1	6.6	6.5	6.1	6.7	6.2	6.3	--	--	--	--	--	--	--	--	--	--	5.6	8.2	6.6	6.3	6.6	6.4	NM	7.2	7.0	6.6	6.9	6.7	
4 Brickyard - 1 (Drainage Course)	6.7	6.7	6.9	6.9	6.9	6.8	6.6	7.3	--	7.0	--	--	--	--	--	--	--	6.3	7.0	6.7	6.7	6.9	6.9	7.0	7.1	7.0	6.8	7.1	7.0	
Knight's Brook - 1 (Upstream in Brook)	NM	NM	NM	NM	7.3	7.0	NM	NM	7.0	NM	NM	7.0	NM	NM	7.2	7.1	NM	NM	7.1	6.9	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Knight's Brook - 2 (Downstream in Brook)	NM	NM	NM	NM	7.5	7.2	NM	NM	7.5	NM	NM	7.4	NM	NM	7.3	7.2	NM	NM	7.2	7.0	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Knight's Brook - 3 (Above Duct Bank in Brook)	NM	NM	NM	NM	7.4	7.2	NM	NM	7.3	NM	NM	7.2	NM	NM	7.2	7.2	NM	NM	7.2	7.1	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Hannah - 1 (Wetland NW-22)	--	NM	--	NM	--	--	NM	NM	--	NM	NM	--	NM	NM	--	--	NM	NM	--	6.3	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Hannah - 2 (Wetland NW-24)	7.2	NM	6.8	NM	7.3	6.8	NM	NM	7.1	NM	NM	--	NM	NM	--	--	NM	NM	--	6.5	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Flynn Pit - 1 (Wetland NW-4)	7.3	NM	6.3	NM	7.1	6.9	NM	NM	7.6	NM	NM	6.5	NM	NM	6.4	5.8	NM	NM	5.8	6.3	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
DURHAM/UNH																														
UNH Wetland - 1 (Stormwater Area)	--	7.8	9.0	--	--	7.7	--	--	--	--	--	--	--	--	--	--	--	--	8.0	--	--	--	--	--	--	--	--	--	--	
UNH Wetland - 2 (Stormwater Area)	--	7.7	8.7	8.0	8.8	7.5	7.5	--	--	--	--	8.1	--	--	--	--	--	8.1	7.3	8.7	8.7	--	--	8.3	--	8.7	--	--	--	
UNH Wetland - 3 (Cattail Wetland)	--	6.7	7.6	--	--	6.6	--	--	--	--	--	--	--	--	--	--	--	--	7.8	7.8	7.8	7.5	7.5	7.6	7.5	7.5	--	--	--	
UNH Wetland - 4 (Cattail Wetland)	6.5	6.8	6.8	6.8	6.7	6.5	6.7	6.3	--	--	--	--	--	--	--	--	--	--	6.6	6.7	6.6	6.7	6.8	6.9	7.0	6.7	--	--	--	
UNH Wetland - 5 (Cattail Wetland)	6.2	6.7	6.9	6.5	6.5	6.2	6.3	--	--	--	--	--	--	--	--	--	--	--	6.9	6.9	6.9	6.7	6.6	6.9	6.9	6.6	--	--	--	
UNH Wetland - 6 (Cattail Wetland)	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	
College Brook - 1 (Upstream in Brook)	7.3	7.1	7.9	7.4	7.4	7.4	7.3	7.7	7.7	7.7	7.5	7.7	7.6	7.7	7.7	7.7	7.6	7.5	7.3	7.4	7.4	7.5	NM	NM	NM	NM	NM	NM	NM	
College Brook - 2 (Downstream in Brook)	7.2	7.3	7.8	7.2	7.3	7.2	7.2	7.5	7.5	7.5	7.3	7.6	7.5	7.5	7.3	7.4	7.4	7.4	7.2	7.0	7.2	7.3	7.4	NM	NM	NM	NM	NM	NM	NM
CB-1 (Catch Basin)	6.8	7.1	7.3	7.1	7.3	7.5	7.2	7.4	7.3	7.3	7.5	7.5	7.5	7.5	7.2	7.3	7.4	7.2	6.3	6.5	6.5	6.5	6.7	NM	NM	NM	NM	NM	NM	NM
CB-2 (Catch Basin)	6.6	6.7	7.2	6.8	6.9	7.3	6.8	6.8	6.7	6.7	6.7	6.7	6.7	6.6	6.8	6.7	6.7	6.6	6.4	6.6	6.7	6.8	6.8	NM	NM	NM	NM	NM	NM	NM
RG - 1 (Rain Garden)	6.9	7.2	7.1	7.0	7.2	7.2	7.3	7.4	7.3	7.3	7.2	7.3	7.0	7.0	7.2	7.3	7.2	7.2	4.3	4.3	4.2	4.4	5.7	6.3	NM	NM	NM	NM	NM	NM
A Lot - 1 (Drainage Swale)	--	--	NM	NM	--	--	NM	NM	--	NM	NM	--	NM	NM	--	--	NM	NM	--	--	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Reservoir Brook (Brook)	7.2	7.0	NM	NM	7.5	7.1	NM	NM	7.6	NM	NM	7.7	NM	NM	7.6	7.6	NM	NM	7.2	6.9	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM

- Notes**
- 1) "NM" indicates location not monitored on this date.
 - 2) "--" indicates area monitored but dry
 - 3) Refer to Daily Drainage Monitoring Report for additional information

EVERSOURCE ENERGY
SEACOAST RELIABILITY PROJECT
TABLE 1
 pH Monitoring
 Newington and Durham, New Hampshire

	WEEK 9			WEEK 10			WEEK 11			WEEK 12		WEEK 13			WEEK 14		WEEK 15		WEEK 16		WEEK 17		WEEK 18		WEEK 19		WEEK 20			
	August 4, 2020	August 5, 2020	August 7, 2020	August 11, 2020	August 12, 2020	August 13, 2020	August 17, 2020	August 18, 2020	August 20, 2020	August 24, 2020	August 25, 2020	August 30, 2020	August 31, 2020	September 3, 2020	September 8, 2020	September 9, 2020	September 11, 2020	September 15, 2020	September 17, 2020	September 22, 2020	September 28, 2020	September 30, 2020	October 2, 2020	October 8, 2020	October 13, 2020	October 14, 2020	October 16, 2020	October 17, 2020	October 19, 2020	October 21, 2020
NEWINGTON																														
29 Gundalow - 1 (Drainage Area)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	
29 Gundalow - 2 (Culvert)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	10.2	9.4	10.3	10.3	9.6
64 Gundalow - 1 (Drainage Course)	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	-	7.4	-	-
64 Gundalow - 2 (Drainage Course)	7.4	6.6	6.6	6.3	6.5	6.6	6.8	6.6	6.3	6.6	6.6	7.3	6.5	6.5	6.7	7.0	6.3	6.5	6.7	-	-	6.5	6.7	6.7	6.4	6.3	6.6	6.8	6.5	6.6
4 Brickyard - 1 (Drainage Course)	7.9	7.1	7.3	7.1	7.8	7.5	7.5	7.2	7.0	7.1	6.9	7.3	6.7	6.9	-	-	6.7	-	-	-	-	6.6	-	6.8	6.5	6.5	6.8	6.7	6.4	6.7
Knight's Brook - 1 (Upstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Knight's Brook - 2 (Downstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Knight's Brook - 3 (Above Duct Bank in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Hannah - 1 (Wetland NW-22)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Hannah - 2 (Wetland NW-24)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Flynn Pit - 1 (Wetland NW-4)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
DURHAM/UNH																														
UNH Wetland - 1 (Stormwater Area)	NM	-	NM	NM	-	NM	-	-	-	-	NM	-	-	-	-	NM	-	-	NM	-	-	-	-	-	-	-	-	-	-	-
UNH Wetland - 2 (Stormwater Area)	NM	-	NM	NM	-	NM	-	-	-	8.1	NM	10.1	-	8.5	-	NM	7.9	-	NM	-	-	8.7	-	-	8.3	8.3	-	7.4	9.6	-
UNH Wetland - 3 (Cattail Wetland)	NM	-	NM	NM	-	NM	-	-	-	-	NM	-	-	-	-	NM	-	-	NM	-	-	-	-	-	6.9	-	-	7.1	7.2	6.9
UNH Wetland - 4 (Cattail Wetland)	NM	-	NM	NM	-	NM	-	-	-	-	NM	-	-	-	-	NM	-	-	NM	-	-	-	-	-	-	-	-	6.9	6.1	5.9
UNH Wetland - 5 (Cattail Wetland)	NM	-	NM	NM	-	NM	-	-	-	-	NM	-	-	-	-	NM	-	-	NM	-	-	-	-	-	-	-	-	6.7	6.2	6.0
UNH Wetland - 6 (Cattail Wetland)	NM	-	NM	NM	-	NM	-	-	-	-	NM	-	-	-	-	NM	-	-	NM	-	-	-	-	-	-	-	-	-	-	-
College Brook - 1 (Upstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
College Brook - 2 (Downstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
CB-1 (Catch Basin)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
CB-2 (Catch Basin)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
RG - 1 (Rain Garden)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
A Lot - 1 (Drainage Swale)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM
Reservoir Brook (Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM

- Notes**
 1) "NM" indicates location not monitored on this date.
 2) "-" indicates area monitored but dry
 3) Refer to Daily Drainage Monitoring Report for additional information

EVERSOURCE ENERGY
SEACOAST RELIABILITY PROJECT
TABLE 1
pH Monitoring
Newington and Durham, New Hampshire

	WEEK 21				WEEK 22			WEEK 23			WEEK 24			WEEK 25			WEEK 26		WEEK 27			WEEK 28		WEEK 29		Week 30		Week 31			
	October 26, 2020	October 28, 2020	October 29, 2020	October 30, 2020	November 2, 2020	November 4, 2020	November 6, 2020	November 10, 2020	November 12, 2020	November 13, 2020	November 16, 2020	November 18, 2020	November 20, 2020	November 23, 2020	November 25, 2020	November 27, 2020	December 1, 2020	December 3, 2020	December 6, 2020	December 8, 2020	December 10, 2020	December 13, 2020	December 15, 2020	December 18, 2020	December 21, 2020	December 23, 2020	December 26, 2020	December 30, 2020	January 3, 2021	January 8, 2021	
NEWINGTON																															
29 Gundalow - 1 (Drainage Area)	--	--	--	--	--	--	--	--	--	--	--	--	6.0	--	--	6.2	--	6.0	--	--	6.3	--	--	--	--	8.6	--	--	--	--	
29 Gundalow - 2 (Culvert)	10.2	10.1	11.2	12.3	12.1	12.5	12.5	12.5	12.5	12.4	12.6	12.8	12.8	11.6	12.5	12.2	10.9	12.3	11.4	12.1	12.6	11.8	12.3	12.6	12.5	12.6	11.3	12.7	12.6	12.7	
64 Gundalow - 1 (Drainage Course)	--	--	--	11.6	11.5	11.8	11.8	11.1	10.6	10.4	12.3	12.7	12.4	10.8	12.1	11.4	9.9	11.8	10.4	11.5	12.0	11.5	11.8	12.3	11.9	12.2	11.1	12.1	12.3	12.4	
64 Gundalow - 2 (Drainage Course)	6.6	6.6	6.7	9.7	9.5	9.3	8.9	7.5	7.3	7.3	10.4	9.4	9.0	9.5	9.3	9.8	8.7	9.2	9.3	9.5	9.6	9.3	9.8	10.0	9.9	9.9	9.2	10.0	10.3	10.5	
4 Brickyard - 1 (Drainage Course)	6.6	6.6	6.7	9.4	9.1	7.1	7.0	7.2	6.8	7.3	9.6	7.2	7.1	9.0	7.4	9.4	7.5	8.1	8.6	9.2	9.3	8.3	9.5	9.3	9.6	9.7	9.0	9.3	9.7	9.8	
4 Brickyard - 2 (Drainage Course)	NM	NM	NM	7.1	7.5	7.3	7.4	7.3	NM	7.3	7.8	7.6	7.5	7.6	7.5	7.8	7.3	7.8	7.7	7.9	7.7	NM	7.9	7.6	7.8	7.7	8.1	7.8	7.9	7.8	
4 Brickyard - 3 (Drainage Course)	NM	NM	NM	7.1	7.3	7.3	7.3	7.2	NM	7.2	7.6	7.5	7.4	7.2	7.4	7.4	6.8	7.5	7.5	7.6	7.6	NM	7.6	7.5	7.5	7.5	7.8	7.5	7.6	7.5	
Knight's Brook - 1 (Upstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Knight's Brook - 2 (Downstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Knight's Brook - 3 (Above Duct Bank in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Hannah - 1 (Wetland NW-22)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Hannah - 2 (Wetland NW-24)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Flynn Pit - 1 (Wetland NW-4)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
DURHAM/UNH																															
UNH Wetland - 1 (Stormwater Area)	--	--	--	--	--	--	--	--	--	--	--	--	--	9.6	--	9.2	8.6	--	8.5	--	--	--	--	--	--	--	9.1	--	--	--	
UNH Wetland - 2 (Stormwater Area)	8.3	8.2	7.5	7.2	7.8	7.6	7.8	--	7.6	7.6	7.6	7.7	7.9	7.3	7.6	7.4	7.6	7.5	7.4	7.4	7.6	7.5	7.5	7.5	--	--	8.0	7.1	7.4	6.9	
UNH Wetland - 3 (Cattail Wetland)	--	7.0	7.2	7.1	7.2	7.3	7.2	7.2	7.1	7.0	7.2	7.5	7.3	7.6	7.7	7.7	7.3	7.6	7.6	8.2	8.1	8.5	7.7	FZ	6.9	7.2	7.8	7.0	7.1	7.2	
UNH Wetland - 4 (Cattail Wetland)	6.0	5.9	5.8	6.2	6.3	6.3	6.3	6.5	6.4	6.3	6.6	6.8	6.5	6.1	6.6	6.5	6.0	6.2	6.3	6.2	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.5	6.4	6.5	6.4
UNH Wetland - 5 (Cattail Wetland)	5.6	5.4	5.4	5.9	6.1	6.4	6.5	6.5	6.2	6.4	6.4	6.4	6.3	6.3	6.3	6.4	5.9	6.2	6.2	5.1	6.2	6.3	6.3	6.5	--	--	7.3	6.5	6.4	6.3	
UNH Wetland - 6 (Cattail Wetland)	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	7.3	--	--	--	
College Brook - 1 (Upstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
College Brook - 2 (Downstream in Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
CB-1 (Catch Basin)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
CB-2 (Catch Basin)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
RG - 1 (Rain Garden)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
A Lot - 1 (Drainage Swale)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	
Reservoir Brook (Brook)	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	NM	

Notes
1) "NM" indicates location not monitored on this date.
2) "--" indicates area monitored but dry
3) "FZ" indicated location monitored but frozen

EVERSOURCE ENERGY
SEACOAST RELIABILITY PROJECT
TABLE 1
pH Monitoring
Newington and Durham, New Hampshire

	WEEK 55		WEEK 56	
	June 28, 2021	July 7, 2021	July 9, 2021	
NEWINGTON				
29 Gundalow - 1 (Drainage Area)	--	--	5.4	
29 Gundalow - 2 (Culvert)	9.6	9.9	5.7	
64 Gundalow - 1 (Drainage Course)	--	--	5.8	
64 Gundalow - 2 (Drainage Course)	7.4	7.2	6.0	
4 Brickyard - 1 (Drainage Course)	7.1	6.8	6.0	
4 Brickyard - 2 (Drainage Course)	--	7.1	5.8	
4 Brickyard - 3 (Drainage Course)	--	7.2	5.9	
Knight's Brook - 1 (Upstream in Brook)	NM	NM	NM	
Knight's Brook - 2 (Downstream in Brook)	NM	NM	NM	
Knight's Brook - 3 (Above Duct Bank in Brook)	NM	NM	NM	
Hannah - 1 (Wetland NW-22)	NM	NM	NM	
Hannah - 2 (Wetland NW-24)	NM	NM	NM	
Flynn Pit - 1 (Wetland NW-4)	NM	NM	NM	
DURHAM/UNH				
UNH Wetland - 1 (Stormwater Area)	--	NM	NM	
UNH Wetland - 2 (Stormwater Area)	--	NM	NM	
UNH Wetland - 3 (Cattail Wetland)	--	NM	NM	
UNH Wetland - 4 (Cattail Wetland)	--	NM	NM	
UNH Wetland - 5 (Cattail Wetland)	--	NM	NM	
UNH Wetland - 6 (Cattail Wetland)	--	NM	NM	
College Brook - 1 (Upstream in Brook)	NM	NM	NM	
College Brook - 2 (Downstream in Brook)	NM	NM	NM	
CB-1 (Catch Basin)	NM	NM	NM	
CB-2 (Catch Basin)	NM	NM	NM	
RG - 1 (Rain Garden)	NM	NM	NM	
A Lot - 1 (Drainage Swale)	NM	NM	NM	
Reservoir Brook (Brook)	NM	NM	NM	

- Notes**
- 1) "NM" indicates location not monitored on this date.
 - 2) "--" indicates area monitored but dry
 - 3) "FZ" indicated location monitored but frozen
 - 4) Refer to Daily Drainage Monitoring Report for additional information